

SERVICE LETTER

SUBJECT: ANGLE OF ATTACK SENSORS

To all Customers and Operators:

Date: May 09/05

This Service Letter is issued to draw attention to the following vendor information:

Rosemount Angle of Attack Sensor Connector - Removal and Installation

Angle of attack (AOA) sensors (975.44.21.421 (Left)) and (975.44.21.422 (Right)) are now superseded by sensors (975.44.21.423 (Left)) and (975.44.21.424 (Right)). The new sensors are supplied with the connector (971.75.16.113) installed on the applicable cable.

Because connectors have not been supplied with the original sensors, the current practice is to remove and retain the connectors when replacing AOA sensors. The removed connector is then installed on the cable of the replacement sensor prior to its installation on the aircraft. The new type sensors make removal and installation of the connectors unnecessary.

Operators are urged to make sure that connectors are not removed from AOA sensors prior to their despatch for replacement.

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD.,
CUSTOMER SUPPORT MANAGER,
CH-6371 STANS,
SWITZERLAND.

General Aviation
Tel : + 41 41 619 6208
Fax: + 41 41 619 7311
eMail: SupportPC12@pilatus-aircraft.com
Government
Tel: + 41 41 619 6509
Fax: + 41 41 619 6224
eMail: rpaterson@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,
PRODUCT SUPPORT DEPARTMENT,
11755 AIRPORT WAY,
BROOMFIELD, CO 80021,
USA

Tel : 303 465 9099
Fax: 303 465 6040
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD.,
PO BOX 732,
MARLESTON SA 5033,
AUSTRALIA

Tel : (08) 8234 4433
Fax: (08) 8234 4499
Free Call: 1800 445 007
eMail: info@pilatus.com.au

