

PILATUS AIRCRAFT LTD. STANS, SWITZERLAND

**SUBJECT: FAA SAIB NE-15-21** 

To all Customers, Operators and Service Centers:

Date: Oct 05/15

Effectivity: All PC-12 aircraft with a fuel nozzle sheath (P/N 3119920-01WE).

This Service Letter is issued to draw attention to the following authority information:

1. The Federal Aviation Administration (FAA) SAIB NE-15-21 dated 19th August 2015.

Pilatus recommends that operators of PC-12 aircraft, read the FAA SAIB NE-15-21 (latest revision) and take the recommended action.

Operators who require further information on this subject should contact the address given below.

PILATUS AIRCRAFT LTD CUSTOMER SUPPORT MANAGER CH-6371 STANS SWITZERLAND

General Aviation Tel: +41 41 619 3333 Fax: +41 41 619 7311

eMail: Supportpc12@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD PRODUCT SUPPORT DEPARTMENT 11755 AIRPORT WAY BROOMFIELD, CO 80021 UNITED STATES OF AMERICA

Tel: +1 303 465 9099 Fax: +1 303 465 6040 eMail: Supportpc12@PilBal.com PILATUS AUSTRALIA PTY LTD 17 JAMES SCHOFIELD DRIVE ADELAIDE AIRPORT SA 5950 AUSTRALIA

Tel: +61 8 8238 1600 Fax: +61 8 8234 4499

Free Call: +61 1800 PILATUS (745 2887) eMail: Supportpc12@pilatus.com.au

#### **Attachments:**

• FAA SPECIAL AIRWORTHINESS INFORMATION BULLETIN NE-15-21





**PC-12** 

INTENTIONALLY BLANK



# SPECIAL AIRWORTHINESS INFORMATION BULLETIN

**SAIB:** NE-15-21

**Date:** August 19, 2015

**SUBJ:** Fuel Injector Nozzle

This is information only. Recommendations aren't mandatory.

#### Introduction

This Special Airworthiness Information Bulletin alerts you, owners, operators, repair stations, and flight standards district offices of a Wencor, LLC, parts manufacturer approval (PMA) supplements 2 and 62, fuel nozzle sheath, part number (P/N) 3119920-01WE, design issue that might impact engine performance and/ or proper installation of the fuel nozzle sheath. Fuel nozzle sheath, P/N 3119920-01WE, replaces original equipment manufacturer (OEM) fuel nozzle sheath, P/N 3119920-01.

At this time, the airworthiness concern is not an unsafe condition that would warrant airworthiness directive action under Title 14 of the Code of Federal Regulations (14 CFR) part 39.

## **Background**

While developing the fuel nozzle sheath, P/N 3119920-01WE, Wencor made the lower portion of the cap thicker than the OEM fuel nozzle sheath, P/N 3119920-01. A technician installing the PMA fuel nozzle sheath, P/N 3119920-01WE, on a PT-6A engine found he/she could not install the part (Figure 1), without it contacting the fuel nozzle (Figure 2) because the fuel nozzle was contacting the sheath.



Figure 1 – Fuel Nozzle Sheath




Figure 2 – Fuel Nozzle inside Cutaway Sheath

A fuel nozzle that is bottomed out in the fuel nozzle sheath might affect the performance, temperature, or integrity of the engine in service. There have been no reports of operational issues to date, but since the fuel nozzle sheaths do not fit with the fuel nozzles as designed, and the effect of this condition is unknown, the FAA recommends removing all Wencor PMA fuel nozzle sheaths, P/N 3119920-01WE, from service.

### Recommendations

- 1. The FAA recommends removing all Wencor PMA fuel nozzle sheaths, P/N 3119920-01WE, from service at the earliest maintenance opportunity not to exceed 600 flight-hours after August 1, 2015.
- 2. The FAA also recommends that all spare Wencor PMA fuel nozzle sheaths, P/N 3119920-01WE, be removed from inventory and not installed in any engine.
- 3. In addition, the FAA recommends that all removed fuel nozzle sheaths and spares be returned to Wencor.

Table 1 – Operators/ Repair Stations Using Fuel Nozzle Sheath, P/N 3119920-01WE

| Operator/ Repair Station       | Country   | Quantity<br>Purchased |
|--------------------------------|-----------|-----------------------|
| Great Lakes Aviation           | USA       | 77                    |
| Prime Turbines (Massachusetts) | USA       | 2                     |
| Prime Turbines (Texas)         | USA       | 4                     |
| Moze Havaclik Savunma Sist.    | Turkey    | 100                   |
| R.T. Turbines, Inc             | USA       | 5                     |
| Division Turbos, SRL           | Argentina | 4                     |

Table 2 – U.S. Type Certified Engine Models Affected with Fuel Nozzle Sheath, P/N 3119920-01WE

| Engine/Model | TCDS No. |  |
|--------------|----------|--|
| PT6A-38      | E4EA     |  |
| PT6A-41      | E4EA     |  |
| PT6A-42      | E4EA     |  |
| PT6A-42A     | E4EA     |  |
| PT6A-45A     | E4EA     |  |
| PT6A-45B     | E4EA     |  |
| PT6A-45R     | E4EA     |  |
| PT6A-50      | E4EA     |  |
| PT6A-60A     | E4EA     |  |
| PT6A-60AG    | E4EA     |  |
| PT6A-61      | E4EA     |  |
| PT6A-64      | E26NE    |  |
| PT6A-65B     | E4EA     |  |
| PT6A-65R     | E4EA     |  |
| PT6A-65AR    | E4EA     |  |
| PT6A-65AG    | E4EA     |  |
| PT6A-67B     | E26NE    |  |
| PT6A-67D     | E26NE    |  |

### **For Further Information Contact**

Matthew Bryant, Aerospace Engineer, Denver Aircraft Certification Office, 26805 East 68<sup>th</sup> Avenue, Room 214, Denver, CO 80249; phone: 303-342-1092; fax: 303-342-1088; email: Matthew.Bryant@faa.gov.

## For Related Service and Warranty Information Contact

Wencor Engineering; phone: 801-491-2543; email: <u>jbies@wencor.com</u>; or Wencor Sales; phone: 801-489-2000; or email: sales@wencor.com.

