SERVICE LETTER

SUBJECT: FUEL CONTROL UNIT - INSPECTION

To all Customers and Operators:

Date: Apr 20/00

This Service Letter is issued to draw attention to the following vendor information:

P&WC SB A14305 - Turboprop Engine - Fuel Control Unit - Inspection of

Woodward SB 60068-73-5 - Engine Fuel and Control - Fuel Control Assembly - Field Inspection of **Tachometer Shaft Concentricity**

PILATUS recommends the incorporation of P&WC SB A14305 and Woodward SB 60068-73-5 because it is necessary to replace all of the Fuel Control Units (FCUs) specified in Woodward SB 60068-73-5.

It is possible for some tachometer shafts to be incorrectly aligned (not concentric) with the applicable FCU bores. This can cause uncommanded increases or decreases of engine power.

Firstly, contact the vendor for specific inquires concerning the subject matter.

Pratt and Whitney Canada Inc. 1000 Marie-Victorin, Longueuil, Quebec, Canada J4G 1A1. Tel: 001 450-677-9411

Operators requiring further information on this subject, please contact the address given below:

PILATUS AIRCRAFT LTD. CUSTOMER LIAISION MANAGER.

CH-6371 STANS, Tel: + 41 41 619 65 09 SWITZERLAND. Fax: + 41 41 610 33 51