



PILATUS AIRCRAFT LTD. CH-6371 STANS, SWITZERLAND

# SERVICE LETTER

**SUBJECT: MAIN LANDING GEAR WHEEL FAIRING**

To all Customers and Operators:

Date: Nov 21/01

This Service Letter is issued to draw attention to the following vendor information:

**BFGoodrich Service Letter (SL) 1881 (Enlarged Fairing Fastener Holes and Introduce New Fastener Screws)**

BFGoodrich SL 1881 alerts Operators of PC12 and PC12/45 aircraft to the possibility of cracks and corrosion in the main landing gear wheel fairings (P/N 31-139OPT2). The damage occurs in the areas around the fastener holes, the surfaces of which are in contact with the attachment screws.

BFGoodrich SL 1881 gives instructions to inspect the wheel fairings for damage and, if no damage is found, to enlarge the fastener holes and replace the attachment screws (P/N NAS1298-3-1, PIL P/N 959.56.01.516). PILATUS recommends Operators to obey BFGoodrich SL 1881 and thus prevent corrosion and crack damage to the wheel fairings.

In the first instance Operators should inquire to:

BFGoodrich,  
Wheel and Brake Division,  
PO. Box 340, Troy, Ohio 45373. Tel: (937) 339 3811

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD.,  
CUSTOMER LIAISON MANAGER,  
CH-6371 STANS,  
SWITZERLAND.

General Aviation  
Tel : + 41 41 619 6319  
Fax: + 41 41 619 6224  
eMail: pilga@pilatus-aircraft.com  
Government  
Tel: + 41 41 619 6509  
Fax: + 41 41 619 6224  
eMail: rpaterson@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,  
PRODUCT SUPPORT DEPARTMENT,  
11755 AIRPORT WAY,  
BROOMFIELD, CO 80021.  
USA

Tel : 303 465 9099  
Fax: 303 465 6040  
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD.,  
PO BOX 732,  
MARLESTON SA 5033,  
AUSTRALIA

Tel : (08) 8234 4433  
Fax: (08) 8234 4499  
Free Call: 1800 445 007  
eMail: info@pilatus.com.au

