



PILATUS AIRCRAFT LTD. CH-6371 STANS, SWITZERLAND

# SERVICE LETTER

**SUBJECT: WINDSHIELD REPAIR**

To all Customers and Operators:

Date: Feb 21/03

This Service Letter (SL) is issued to draw attention to the following information:

**Service Letter 049 - PPG Industries Service Information Letter 172121-001 - Repair of De-bonded Outboard Fiberglass Strap on Glass Windshields**

This SL supersedes SL 049.

The purpose of SL 049 was to refer Operators to PPG Industries Service Information Letter (SIL) 172121-001 for the repair of de-bonded fiberglass straps on glass windshields. An equivalent reference to SIL 172121-001 is now contained in the Aircraft Maintenance Manual, 56-00-00 which makes the reference given in SL 049 unnecessary.

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD.,  
CUSTOMER LIAISON MANAGER,  
CH-6371 STANS,  
SWITZERLAND.

General Aviation  
Tel : + 41 41 619 6319  
Fax: + 41 41 619 6224  
eMail: pilga@pilatus-aircraft.com  
Government  
Tel: + 41 41 619 6509  
Fax: + 41 41 619 6224  
eMail: rpaterson@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,  
PRODUCT SUPPORT DEPARTMENT,  
11755 AIRPORT WAY,  
BROOMFIELD, CO 80021.  
USA

Tel : 303 465 9099  
Fax: 303 465 6040  
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD.,  
PO BOX 732,  
MARLESTON SA 5033,  
AUSTRALIA

Tel : (08) 8234 4433  
Fax: (08) 8234 4499  
Free Call: 1800 445 007  
eMail: info@pilatus.com.au

**Attachments: None.**

