

SERVICE LETTER

SUBJECT: PILOTS OPERATING HANDBOOK - CHANGES TO THE GENERATOR 2 LOAD OUTPUTS

To all Customers and Operators:

Date: Feb 23/04

This Service Letter is issued to draw attention to the following information:

Pilots Operating Handbook (POH) - Changes to the Generator 2 Load Outputs in Sections 2 and 3.

PILATUS has been made aware of the fact that some operators do not realize that the output loads, in the POH, for the No. 2 generator have been reduced.

The maximum generator load limits for the No. 2 (Second) Generator in the POH (Section 2 - Limitations) have changed as follows:

MAX CONTINUOUS LOAD - Was 130 AMP, changed to 115 AMP MAX LOAD FOR 2 MINUTES - Was 145 AMP, changed to N/A.

This change has impacted on the Emergency Procedures (Section 3) as follows:

MSN 101 thru 320 and MSN 322 thru 400:

Para. 3.15.3, Sub. Para. 5

Was "GEN 2 load- Reduce to below 130 amp", changed to "Electrical load - Reduce until battery current is positive (not discharging)".

MSN 321 and MSN 401 and subsequent:

Para. 3.15.3, Sub. Para. 4

Was "GEN 2 load- Reduce to below 130 amp", changed to "Electrical load - Reduce until battery current is positive (not discharging)".

Operators are requested to make sure that this Service Letter is brought to the attention of their aircrew.



Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD., CUSTOMER SUPPORT MANAGER, CH-6371 STANS, SWITZERLAND.

General Aviation Tel: + 41 41 619 6208 Fax: + 41 41 619 7311

eMail: SupportPC12@pilatus-aircraft.com

Government Tel: +41 41 619 6509 Fax: + 41 41 619 6224

eMail: rpaterson@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD., PRODUCT SUPPORT DEPARTMENT, 11755 AIRPORT WAY, BROOMFIELD, CO 80021.

Tel: 303 465 9099

Fax: 303 465 6040 eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD., PO BOX 732, MARLESTON SA 5033, AUSTRALIA

Tel: (08) 8234 4433 Fax: (08) 8234 4499 Free Call: 1800 445 007 eMail: info@pilatus.com.au