



PILATUS AIRCRAFT LTD. CH-6371 STANS, SWITZERLAND

SERVICE LETTER

SUBJECT: CHANGE TO THE GREASE TYPE FOR SAUTER BACHMANN FLAP ACTUATORS

To all Customers, Operators and Maintenance Units:

Date: Jul 21/04

This Service Letter is issued to draw attention to the following vendor information:

SAUTER BACHMANN FLAP ACTUATORS - CHANGE TO THE GREASE TYPE

The grease currently used in the flap actuators (made by Sauter-Bachmann), Pilatus P/Ns 978.73.20.307 and 978.73.20.308, is NCA 51 (Material No. P04-032 - Pilatus P/N 908.21.42.115).

To get better results in cold temperatures, this grease must be replaced with Aeroshell 33 (Material No. P04-028 - Pilatus P/N 908.20.02.065),

This Service Letter is issued to advise all Customers, Operators and Maintenance Units of the change in the type of grease used to lubricate the flap actuators. The AMM procedure (Ref. 27-50-00, Page Block 301), for the lubrication of the flap actuators, will be amended to show the change in the type of grease.

The latest flap actuator (made by Sauter-Bachmann), Pilatus P/N 978.73.20.309, has the new type grease incorporated during manufacture and must not be lubricated with the older type grease (Material No. P04-032 - Pilatus P/N 908.21.42.115).

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD.,
CUSTOMER SUPPORT MANAGER,
CH-6371 STANS,
SWITZERLAND.

General Aviation
Tel : + 41 41 619 6208
Fax: + 41 41 619 7311
eMail: SupportPC12@pilatus-aircraft.com
Government
Tel: + 41 41 619 6509
Fax: + 41 41 619 6224
eMail: rpaterson@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,
PRODUCT SUPPORT DEPARTMENT,
11755 AIRPORT WAY,
BROOMFIELD, CO 80021,
USA

Tel : 303 465 9099
Fax: 303 465 6040
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD.,
PO BOX 732,
MARLESTON SA 5033,
AUSTRALIA

Tel : (08) 8234 4433
Fax: (08) 8234 4499
Free Call: 1800 445 007
eMail: info@pilatus.com.au

