SERVICE LETTER

SUBJECT: PASSENGER DOOR

To all Customers and Operators:

This Service Letter is issued to draw attention to the following information:

Passenger Door - Internal Corrosion

Operators of PC-12 and PC-12/45 aircraft should be aware of the possibility of corrosion occurring in the passenger door interior. The corrosion is caused when salt laden water enters the interior of the door during passenger loading in certain environmental conditions. Severe damage to the door could occur if such corrosion is neglected.

Changes to the inspection criteria (Ref: Aircraft Maintenance Manual, 05-10-20) will be implemented to reduce the risk of corrosion damage.

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD., CUSTOMER SUPPORT MANAGER, CH-6371 STANS, SWITZERLAND.

General Aviation Tel: + 41 41 619 6208 Fax: + 41 41 619 7311 eMail: SupportPC12@pilatus-aircraft.com Government

Tel: + 41 41 619 6509 Fax: + 41 41 619 6224

eMail: rpaterson@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD., PRODUCT SUPPORT DEPARTMENT, 11755 AIRPORT WAY, BROOMFIELD, CO 80021. USA

Tel: 303 465 9099 Fax: 303 465 6040

eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD., PO BOX 732, MARLESTON SA 5033, AUSTRALIA

Tel: (08) 8234 4433 Fax: (08) 8234 4499 Free Call: 1800 445 007 eMail: info@pilatus.com.au Date: Feb 22/05