

SERVICE LETTER

SUBJECT: PRATT & WHITNEY CANADA SERVICE BULLETIN 14351

To all Customers and Operators:

Date: Feb 22/06

This Service Letter is issued to draw attention to the following vendor information:

Pratt & Whitney Canada Service Bulletin 14351: Turboprop Engine Propeller Shaft Seal - Replacement of

Oil leakage can occur at the propeller-shaft plain seal in PT6A-67B engines. Pratt & Whitney Canada (P&WC) have issued Service Bulletin (SB) 14351 to address this problem.

PILATUS recommends replacement of the seal at the next available opportunity in accordance with the recommendations given in P&WC SB: 14351, Sect 1, E (Compliance).

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD.,
CUSTOMER SUPPORT MANAGER,
CH-6371 STANS,
SWITZERLAND.

General Aviation
Tel: + 41 41 619 6208
Fax: + 41 41 619 7311
eMail: SupportPC12@pilatus-aircraft.com
Government
Tel: + 41 41 619 6226
Fax: + 41 41 619 6170
eMail: snolan@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,
PRODUCT SUPPORT DEPARTMENT,
11755 AIRPORT WAY,
BROOMFIELD, CO 80021.
USA

Tel : 303 465 9099
Fax: 303 465 6040
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD.,
17 James Schofield Drive,
Adelaide Airport SA 5950,
AUSTRALIA

Tel : +61 (08) 8234 4433
Fax: +61 (08) 8234 4499
Free Call: 1800 445 007
eMail: info@pilatus.com.au