

SERVICE LETTER

SUBJECT: PRATT & WHITNEY CANADA SERVICE INFORMATION LETTER NO. PT6A-143

To all Customers and Operators:

Date: Jun 29/07

This Service Letter is issued to draw attention to the following vendor information:

**PRATT & WHITNEY CANADA SERVICE INFORMATION LETTER (P&WC SIL) NO. PT6A-143 - PT6A-67B
FUEL CONTROL BELLOWS REPLACEMENT.**

P&WC SIL No. PT6A-143 is issued to tell all operators that P&WC Service Bulletin (SB) 14371 (Fuel Control Bellows Replacement) has been accomplished on all affected aircraft. But there are 14 Fuel Control Units (FCUs) held as spares that have not been modified. The locations of the 14 FCUs are not known. P&WC SIL No. PT6A-143 lists the serial numbers of the 14 pre SB 14371 FCUs. Operators must check the serial number when a replacement FCU is to be installed to make sure it is post SB 14371.

A Caution has been included in the Engine Maintenance Manual to instruct personnel to check the serial number when a replacement FCU is to be installed.

Pilatus fully supports the content of P&WC SIL No. PT6A-143 as installation of a pre SB 14371 FCU could result in engine failure.

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD.,
CUSTOMER SUPPORT MANAGER,
CH-6371 STANS,
SWITZERLAND.

General Aviation
Tel : + 41 41 619 6208
Fax: + 41 41 619 7311
eMail: SupportPC12@pilatus-aircraft.com
Government
Tel: + 41 41 619 6226
Fax: + 41 41 619 6170
eMail: snolan@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,
PRODUCT SUPPORT DEPARTMENT,
11755 AIRPORT WAY,
BROOMFIELD, CO 80021.
USA

Tel : 303 465 9099
Fax: 303 465 6040
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD.,
17 James Schofield Drive,
Adelaide Airport SA 5950,
AUSTRALIA

Tel : +61 (08) 8234 4433
Fax: +61 (08) 8234 4499
Free Call: 1800 445 007
eMail: info@pilatus.com.au

Attachments: P&WC SIL No. PT6A-143

PILATUS
PC12
SERVICE LETTER

INTENTIONALLY BLANK



SERVICE INFORMATION LETTER

Subject PT6A-67B Fuel Control Bellows Replacement

Applicability PT6A-67B Engines


This Service Information Letter (SIL) is issued to advise all operators that SB 14371 originally issued to replace the Fuel Control Unit (FCU) bellows has now been accomplished on all affected aircraft. We would like to take this opportunity to thank everyone for their cooperation in scheduling and incorporating Service Bulletin 14371.

Although all affected aircraft have been updated there are still fourteen (14) spare units that need to have the SB incorporated. Unfortunately their locations are presently unknown to Pratt & Whitney Canada Corp. (P&WC). A list of the affected FCU's serial numbers is included in Table 1 on page 2 of this SIL.

Because of the possibility that a Pre SB14371 FCU could be installed as a spare/replacement unit, P&WC has issued a revision to the Engine Maintenance Manual. Adding a caution note, that when installing a replacement FCU, confirm that the FCU is in fact, a post SB14371 unit.

Yours truly,

PRATT & WHITNEY CANADA CORP.


Giovanni Mulas
Manager, Small Turboprops
Customer Support

This Service Information Letter is valid until superceded or cancelled by revision.

ISSUED: 04 December 2006

Page 1 of 2

**PRATT & WHITNEY CANADA
SERVICE INFORMATION LETTER**

SIL No. PT6A-143

TABLE 1

FCU P/N	P&WC P/N	S/N
8063-041	3119892-03	2336350
8063-041	3119892-03	11420316
8063-041	3119892-03	12017020
8063-041	3119892-03	12049485
8063-041	3119892-03	12091089
8063-041	3119892-03	12100536
8063-041	3119892-03	12120173
8063-041	3119892-03	12151777
8063-041	3119892-03	12198108
8063-041	3119892-03	12229143
8063-041	3119892-03	12247758
8063-041	3119892-03	12287028
8063-042	3119892-04	13001261
8063-042	3119892-04	13309211

This Service Information Letter is valid until superseded or cancelled by revision.

ISSUED: 04 December 2006

Page 2 of 2