

SUBJECT: All PC12 Series Aircraft - Vendor Modifications for Crew Seats

To all Customers, Operators and Service Centers:

Date: Jun 17/11

This Service Letter is issued to draw attention to the following information:

Effective from PC-12 MSN 661 to 683, the IPECO Crew Seats were introduced with a replacement interval on the seat cushion of 3 years (Part No. 0A318-02-02 installed on IPECO Seat PIL P/N 959.30.01.135 and 959.30.01.136). Refer to Aircraft Maintenance Manual - Time Limits Task 25-10/293.

The seat vendor has now issued Service Bulletin 318-25-06 allowing to upgrade the crew seats from:

- PIL P/N 959.30.01.135 to 959.30.01.163
- PIL P/N 959.30.01.136 to 959.30.01.164.

The previous life limitation on the seat cushion is no longer applicable to the new seat cushion Part No. 0A318-0569.

NOTE: The IPECO Service Bulletin is available on:
www.pilatus-aircraft.com > Customer Support > Publications > PC-12
> Third Party Documents.

NOTE: The required IPECO CMMs are available on the Pilatus CMM CD-ROM Pub. No. 02258.

For price and availability, please contact IPECO directly using the contact information given in the IPECO Service Bulletin.

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD.,
CUSTOMER SUPPORT MANAGER,
CH-6371 STANS,
SWITZERLAND.

General Aviation
Tel : + 41 41 619 3333
Fax: + 41 41 619 7311
eMail: SupportPC12@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,
PRODUCT SUPPORT DEPARTMENT,
11755 AIRPORT WAY,
BROOMFIELD, CO 80021.
USA

Tel : 303 465 9099
Fax: 303 465 6040
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD.,
17 James Schofield Drive,
Adelaide Airport SA 5950,
AUSTRALIA

Tel : +61 (08) 8234 4433
Fax: +61 (08) 8234 4499
Free Call: 1800 445 007
eMail: SupportPC12@pilatus.com.au

INTENTIONALLY BLANK