

SUBJECT: FCU Bellows Life Limit, PT6A-67B and PT6A-67P

Date: Aug 13/13

To all Pilatus Customers, Operators and Service Centers (Maintenance Organizations).

Applicability: PT6A-67B and PT6A-67P PWC engines.

This Service Letter is issued to draw attention to the following information:

PWC has changed the life limit for the replacement of the Fuel control Unit (FCU) bellows. The FCU bellows is limited to 4000 hours. The bellows must be replaced every 4000 hours regardless of the FCU Time Between Overhaul (TBO). For more information, refer to the PWC Service Bulletin 14603, latest revision.

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD.,
CUSTOMER SUPPORT MANAGER,
CH-6371 STANS,
SWITZERLAND.

General Aviation
Tel : + 41 41 619 3333
Fax: + 41 41 619 7311
eMail: SupportPC12@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,
PRODUCT SUPPORT DEPARTMENT,
11755 AIRPORT WAY,
BROOMFIELD, CO 80021.
USA

Tel : 303 465 9099
Fax: 303 465 6040
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD.,
17 James Schofield Drive,
Adelaide Airport SA 5950,
AUSTRALIA

Tel : +61 (08) 8234 4433
Fax: +61 (08) 8234 4499
Free Call: 1800 445 007
eMail: SupportPC12@pilatus.com.au