

**SUBJECT: P&WC SERVICE BULLETIN No.14507**

To all Customers, Operators and Service Centers:

Date: Aug 17/15

Effectivity: All PC-12 aircraft with a PT-6A-67B or PT6-A67P engine.

This Service Letter is issued to draw attention to the following vendor information:

P&amp;WC have issued a service bulletin to advise operators to do a onetime inspection of the interconnect rod for proper installation of the safety cable.

Pilatus recommends that operators of PC-12 aircraft, read the P&amp;WC Service Bulletin No.14507 (latest revision) and take the recommended action.

Operators who require further information on this subject should contact the address given below.

PILATUS AIRCRAFT LTD  
CUSTOMER SUPPORT MANAGER  
CH-6371 STANS  
SWITZERLAND  
General Aviation  
Tel: +41 41 619 3333  
Fax: +41 41 619 7311  
eMail: SupportPC12@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD  
PRODUCT SUPPORT DEPARTMENT  
11755 AIRPORT WAY  
BROOMFIELD, CO 80021  
UNITED STATES OF AMERICA  
Tel: +1 303 465 9099  
Fax: +1 303 465 6040  
eMail: Supportpc12@PilBal.com

PILATUS AUSTRALIA PTY LTD  
17 JAMES SCHOFIELD DRIVE  
ADELAIDE AIRPORT SA 5950  
AUSTRALIA  
Tel: +61 8 8238 1600  
Fax: +61 8 8234 4499  
Free Call: +61 1800 PILATUS (745 2887)  
eMail: Supportpc12@pilatus.com.au

**Attachments:**

- P&WC SERVICE BULLETIN No.14507