

SUBJECT: ENGINE - 2ND STAGE POWER TURBINE (PT2) BLADE FAILURE (TCCA AD CF-2024-05)

To all Customers, Operators and Service Centers:

Date: Feb 16/24

Effectivity: All PC-12 Series Aircraft

This Service Letter is issued to draw attention to Emergency Airworthiness Directive (AD) CF-2024-05 issued by the Transport Canada Civil Aviation (TCCA) Directorate.

Pilatus provides the following additional information to support operators in understanding the compliance effectivity of the above referenced documents:

- Pilatus has contained and contacted all operators of new engines with less than 50 flight hours Total Time Since New (TTSN).
- The AD CF-2024-05 is applicable to operators that have had a second stage power turbine overhaul or repair and have less than 50 flight hours since completion of the overhaul/repair.

For full information on this subject, refer to TCCA AD CF-2024-05.

Operators that require additional information should contact their authorized Pilatus Service Center, or Pilatus Customer Support on www.pilatus-aircraft.com → contact us.

INTENTIONALLY BLANK