

SERVICE LETTER

SUBJECT: P&WC SERVICE INFORMATION LETTER PT6A-035 PROPELLER GOVERNOR -
ECCENTRIC COVER SCREW REPLACEMENT AND WOODWARD SERVICE
BULLETIN 33606 (PROPELLER GOVERNOR ECCENTRIC COVER SCREW
REPLACEMENT)

All Operators:

Date: July 09/97

This service letter draws the attention of customers to Vendor information that provides full details on the above topics as follows:

APPENDIX A P&WC Service Information Letter PT6A-035 -- Propeller Governor, Eccentric Screw Replacement.

APPENDIX B Woodward Service Bulletin 33606 -- Propeller Governor Eccentric Cover Screw Replacement.

NOTE: Operators are advised to verify the list against their inventories to identify units assembled with suspect screws on PGU (PIL. P/N: 968.20.13.160) - (WGC P/N: 8210-137).

Firstly, contact the Vendor for any specific inquiries concerning the subject matter.

If you have difficulty, make inquires at the following address:

PILATUS AIRCRAFT LTD.
CUSTOMER LIAISON MANAGER,
CH-6371 STANS,
SWITZERLAND.

Tel: +41 41 619 6509
Fax: +41 41 610 3351

≡PILATUS≡
PC12
SERVICE LETTER

INTENTIONALLY BLANK

≡PILATUS≡
PC12
SERVICE LETTER

Appendix A to Pilatus Service Letter No. 021

(P&WC Service Information Letter PT6A-035, Dated 24 Feb /97)

≡PILATUS≡
PC12
SERVICE LETTER

INTENTIONALLY BLANK



SERVICE INFORMATION LETTER

Subject Propeller Governor - Eccentric Cover Screw Replacement

Applicability PT6A-10, -11, -11AG, -15AG, -20A, -20B, -21, -25, -25A, -25C, -27, -28, -34, -34AG, -34B, -36, -38, -41, -41AG, -42, -45A, -45B, -45R, -60A, -61, -64, -65AG, -65AR, -65B, -65R, -67B, -110, -112, -114, -114A, -116, -135, -135A

This SIL is introduced to advise operators of Service Bulletin (S.B.) 33606 being issued by Woodward Governor Company (WGC) on a number of Propeller Governor Units (PGU) used on various PT6A engines. There have been three incidents during in-house testing where one of the eccentric cover screws broke on the PGU; none of these incidents occurred in-flight, or in the field.

Screw failures to date have been attributed to cracking induced by embrittlement. Should both retaining screws break, a change in the underspeed pneumatic limiter (pneumatic minimum adjustment) of the propeller may occur, modifying the propeller speed limits in beta mode. This change does not affect the normal operation of the aircraft in flight.

WGC S.B. 33606 provides instructions for the replacement of the screws, and includes a comprehensive support plan for affected units in the field. The replacement screws are of a different material and not prone to embrittlement. A list of PGU's, detailing part numbers and serial numbers of units manufactured or overhauled at WGC, is attached to the S.B. All PT6A operators are requested to verify the list against their inventories to identify those units assembled with suspect screws.

Yours truly,

R. Day
for R. Day
Manager, Accessories Technical Support

This Service Information Letter is valid for one year from date of issue.

Issued: 24 Feb. /97

1000, Marie-Victorin, Longueuil, Québec
Canada J4G 1A1

≡PILATUS≡
PC12
SERVICE LETTER

Appendix B to Pilatus Service Letter No. 021

(Woodward Service Bulletin 33606 --
Propeller Governor Eccentric Cover Screw Replacement)

≡PILATUS≡
PC12
SERVICE LETTER

INTENTIONALLY BLANK

Propeller Governor Eccentric Cover Screw Replacement**1. Summary**

Replace eccentric cover screws on potentially affected governors per instructions provided in this Service Bulletin. Potentially affected governors have two (2) zinc-plated cover screws which may exhibit embrittlement or stress corrosion, which can lead to breakage of the screw. Three (3) screws from a lot of 4000 have broken. A list of serial numbers of potentially affected governors is included in this service bulletin.

2. Planning Information**A) Effectivity**

Turboprop governor models 8210-002, 8210-003, 8210-004, 8210-006, 8210-007, 8210-024, 8210-025, 8210-027, 8210-033, 8210-034, 8210-133, 8210-137, 8210-209, 8210-212

B) Concurrent Requirements

None

C) Reason

- i) The affected socket head screws may crack or break. Breakage of screws may cause loose parts in the engine compartment. Misadjustment of the underspeed pneumatic limiter is also possible. Misadjustment can be identified by a change in maximum speed in reverse or beta mode. Broken screws can typically be identified by visual inspection of the governor.
- ii) Cause - Embrittlement or stress corrosion of the screw.
- iii) Solution - Replace screws on affected units.

D) Description

Replace two (2) plated screws (WGC p/n 1039-220) with two (2) non-plated stainless steel screws (WGC p/n 1039-402) on the affected governors. The procedure for screw replacement is provided in section 4 below. If screws are broken or break during removal and removal of the screw is not possible, contact Woodward Governor Company to obtain a replacement governor. See section 3, Material Information, for further details.

33606Page 1 of 14
Feb 21/97

E) Compliance

CODE 5: Accomplish when the governor is accessible during disassembly of an engine or engine module, and when the governor is at a component shop.

F) Approval

Technical aspects of this bulletin have been FAA approved.

G) Manpower

Screw replacement will require approximately 15 minutes per governor.

H) Weight and Balance

Not Affected.

I) Electrical Load Data

Not Affected.

J) Software Accomplishment Summary

Not affected.

K) References

Woodward Governor Company Engineering Change 1000425.

L) Other Publications Affected

Propeller Governor Component Maintenance Manuals 33163, 33167, WG60020, WG60021, WG60022, WG60044, WG60045, WG60046, and WG60074.

33606



SERVICE BULLETIN

WOODWARD GOVERNOR COMPANY
 AIRCRAFT CONTROLS GROUP
 One Woodward Way
 P.O. Box 405
 Rockton, Illinois 61072-0405
 USA

3. Material Information

<u>New Part Number</u>	<u>Quantity</u>	<u>Old Part Number</u>	<u>Disposition of Old Part</u>
1039-402	2	1039-220	Replace

Woodward Governor Company will supply the two replacement screws free of charge on potentially affected governors (see attached list of serial numbers). Woodward Governor Company will provide a replacement governor in the event that a broken screw cannot be removed from the governor. Contact Woodward Governor Company for replacement parts or governors.

Woodward Governor Company
 Aircraft Controls Group
 One Woodward Way
 Box 405
 Rockton, IL 61072-0405
 USA
 Telephone: (815) 624-4400
 Facsimile: (815) 624-6765

Woodward Governor (U.K.) Ltd.
 350 Basingstoke Road
 Reading, Berkshire
 RG2 0NY
 ENGLAND
 Telephone: 44 (0) 118 9752727
 Facsimile: 44 (0) 118 9751599

4. ACCOMPLISHMENT INSTRUCTIONS

NOTE: Replacement of the screws may be performed with the governor on or off the engine. Always maintain torque on at least one screw to prevent movement of the eccentric adjustment.

- A) Remove all anti-tamper seal from the affected eccentric adjustment screw area.
- B) Remove the lockwire from both cover plate screws.
- C) Loosen and remove one of the cover screws. DO NOT loosen the other screw until the replacement screw has been installed.
- D) Lubricate replacement screw threads with Naphthenic oil, non-additive ISO viscosity, grade 1000.
- E) Install one of the new screws in place of the screw removed in step C.
- F) Tighten the new screw to between 4 and 8 in-lbs.
- G) Loosen and remove the other cover screw.
- H) Install a new screw and tighten to 4 - 8 in-lbs.

33606

- I) Alternately tighten the eccentric cover screws until torque on each screw is between 10 and 14 in-lbs.
- J) Lockwire through both new screws.
- K) Identify the modified governor by marking the nameplate. If governor is at its latest revision per the table below, scratch the current revision letter and stamp the new revision letter on the nameplate. If the governor is not at the latest revision per the table below then stamp a slash (/) after the old governor revision letter followed by the new revision letter as indicated in the table below. SB33606 may be marked on the nameplate as an alternate method of identification.
- L) Return broken screws and the serial number of the governor to Woodward Governor Company. Unbroken screws (p/n 1039-220) may be discarded.

PARTS REQUIRED: 2 socket head cap screws, p/n 1039-402, will be provided for replacement on each affected governor as listed on the GOVERNORS AFFECTED list.

TABLE OF GOVERNOR REVISION LETTERS

Governor Model	Current Revision	Revision to be marked upon completion of this Service Bulletin
8210-002	AD	AE
8210-003	T	U
8210-004	T	U
8210-006	H	J
8210-007	F	G
8210-024	G	H
8210-025	F	G
8210-027	C	D
8210-033	E	F
8210-034	H	J
8210-133	B	C
8210-137	B	C
8210-209	C	D
8210-212	D	E

33606

WOODWARD

®

SERVICE BULLETIN

WOODWARD GOVERNOR COMPANY
 AIRCRAFT CONTROLS GROUP
 One Woodward Way
 P.O. Box 405
 Rockton, Illinois 61072-0405
 USA

1. New Governors Affected

<u>SERIAL NO.</u>	<u>ITEM NO.</u>	<u>DATE</u>	<u>S/O #</u>	<u>SERIAL NO.</u>	<u>ITEM NO.</u>	<u>DATE</u>	<u>S/O #</u>
11501352	8210-002	22-Mar-96	1082327	11517841	8210-024	13-Sep-96	1132965
11501353	8210-002	22-Mar-96	1082327	11517842	8210-024	12-Sep-96	1132967
11501354	8210-002	22-Mar-96	1082327	11517843	8210-024	13-Sep-96	1132969
11501569	8210-002	25-Mar-96	1082327	11517844	8210-024	4-Oct-96	1138980
11501570	8210-002	25-Mar-96	1082327	11517845	8210-024	27-Nov-96	1149618
11501571	8210-002	25-Mar-96	1082327	11517846	8210-024	16-Oct-96	1141397
11501572	8210-002	25-Mar-96	1082327	11518126	8210-024	16-Oct-96	1141394
11501573	8210-002	25-Mar-96	1082327	11518351	8210-024	4-Jun-96	1082330
11501574	8210-002	25-Mar-96	1082327	11519012	8210-024	5-Jun-96	1082330
11501575	8210-002	25-Mar-96	1082327	11519545	8210-024	7-Jun-96	1082330
11501576	8210-002	25-Mar-96	1082327	11519546	8210-024	12-Jul-96	1082330
11501577	8210-002	25-Mar-96	1082327	11519547	8210-024	12-Jul-96	1082330
11501578	8210-002	25-Mar-96	1082327	11531158	8210-024	26-Jul-96	1082330
11501579	8210-002	25-Mar-96	1082327	11531230	8210-024	26-Jul-96	1082330
11501580	8210-002	25-Mar-96	1082327	11533832	8210-024	7-Aug-96	1082330
11501809	8210-002	27-Mar-96	1082327	11533833	8210-024	7-Aug-96	1082330
11501810	8210-002	27-Mar-96	1082327	11534885	8210-024	12-Aug-96	1082330
11501811	8210-002	27-Mar-96	1082327	11534886	8210-024	12-Aug-96	1082330
11501812	8210-002	27-Mar-96	1082327	11538294	8210-024	27-Aug-96	1082330
11502397	8210-002	29-Mar-96	1082327	11538295	8210-024	27-Aug-96	1082330
11502398	8210-002	29-Mar-96	1082327	11538296	8210-024	27-Aug-96	1082330
11502399	8210-002	29-Mar-96	1082327	11538297	8210-024	22-Jan-97	1144845
11502400	8210-002	29-Mar-96	1082327	11539605	8210-024	30-Aug-96	1082330
11508969	8210-002	30-Apr-96	1082327	11541507	8210-024	9-Sep-96	1082330
11508970	8210-002	30-Apr-96	1082327	11541508	8210-024	9-Sep-96	1082330
11508971	8210-002	30-Apr-96	1082327	11893712	8210-024	30-Sep-96	1082330
11509227	8210-002	1-May-96	1082327	11893713	8210-024	30-Sep-96	1082330
11509228	8210-002	1-May-96	1082327	11894004	8210-024	30-Sep-96	1082330
11509229	8210-002	1-May-96	1082327	11894005	8210-024	30-Sep-96	1082330
11509230	8210-002	1-May-96	1082327	11894380	8210-024	1-Oct-96	1082330
11509231	8210-002	1-May-96	1082327	11894381	8210-024	1-Oct-96	1082330
11509480	8210-002	3-May-96	1082327	11898166	8210-024	18-Oct-96	1082330
11509481	8210-002	3-May-96	1082327	11898167	8210-024	18-Oct-96	1082330
11509482	8210-002	3-May-96	1082327	11898168	8210-024	18-Oct-96	1082330
11509483	8210-002	3-May-96	1082327	11898169	8210-024	18-Oct-96	1082330
11509484	8210-002	3-May-96	1082327	11898170	8210-024	28-Oct-96	1082330
11509485	8210-002	3-May-96	1082327	11904466	8210-024	8-Nov-96	1082330
11509486	8210-002	3-May-96	1082327	11906567	8210-024	14-Nov-96	1082330
11509486	8210-002	30-Oct-96	1140724	11906568	8210-024	14-Nov-96	1082330
11509785	8210-002	3-May-96	1082327	11906569	8210-024	19-Nov-96	1148141
11509786	8210-002	3-May-96	1082327	11906570	8210-024	3-Dec-96	1149178
11509787	8210-002	3-May-96	1082327	11908452	8210-024	3-Dec-96	1149178
11509788	8210-002	3-May-96	1082327	11915534	8210-024	30-Dec-96	1149178

33606



SERVICE BULLETIN

WOODWARD GOVERNOR COMPANY
 AIRCRAFT CONTROLS GROUP
 One Woodward Way
 P.O. Box 405
 Rockton, Illinois 61072-0405
 USA

<u>SERIAL NO.</u>	<u>ITEM NO.</u>	<u>DATE</u>	<u>S/O #</u>	<u>SERIAL NO.</u>	<u>ITEM NO.</u>	<u>DATE</u>	<u>S/O #</u>
11510165	8210-002	6-May-96	1082327	11915535	8210-024	6-Jan-97	1152516
11510166	8210-002	6-May-96	1082327	11915536	8210-024	6-Jan-97	1152516
11510167	8210-002	6-May-96	1082327	11915537	8210-024	7-Jan-97	1152516
11510168	8210-002	6-May-96	1082327	11915538	8210-024	7-Jan-97	1152516
11510169	8210-002	6-May-96	1082327	11918757	8210-024	7-Jan-97	1152516
11510395	8210-002	7-May-96	1111686	11924037	8210-024	29-Jan-97	1152516
11511788	8210-002	8-May-96	1111796	11924038	8210-024	29-Jan-97	1152516
11517442	8210-002	3-Sep-96	1123877	11924039	8210-024	29-Jan-97	1152516
11517443	8210-002	30-May-96	1082327	11925846	8210-024	7-Feb-97	1152516
11517444	8210-002	3-Sep-96	1126510	11925847	8210-024	7-Feb-97	1152516
11517445	8210-002	30-May-96	1082327	11504193	8210-025	30-Apr-96	1082331
11517446	8210-002	30-May-96	1082327	11504194	8210-025	30-Apr-96	1082331
11517447	8210-002	11-Jun-96	1082327	11505178	8210-025	30-Apr-96	1082331
11517448	8210-002	11-Jun-96	1082327	11505179	8210-025	13-May-96	1082331
11517449	8210-002	8-Jul-96	1082327	11505180	8210-025	26-Jul-96	1082331
11517450	8210-002	8-Jul-96	1082327	11516741	8210-025	28-May-96	1082331
11517451	8210-002	8-Jul-96	1082327	11516742	8210-025	28-May-96	1082331
11517452	8210-002	8-Jul-96	1082327	11516743	8210-025	28-May-96	1082331
11518662	8210-002	5-Jun-96	1082327	11518523	8210-025	4-Jun-96	1082331
11518663	8210-002	5-Jun-96	1082327	11518524	8210-025	4-Jun-96	1082331
11518664	8210-002	5-Jun-96	1082327	11518525	8210-025	4-Jun-96	1082331
11523588	8210-002	18-Sep-96	1132971	11518526	8210-025	4-Jun-96	1082331
11526999	8210-002	8-Jul-96	1082327	11518527	8210-025	4-Jun-96	1082331
11527000	8210-002	8-Jul-96	1082327	11522009	8210-025	9-Aug-96	1082331
11527001	8210-002	12-Jul-96	1082327	11522009	8210-025	31-Oct-96	1142304
11527002	8210-002	12-Jul-96	1082327	11522010	8210-025	9-Aug-96	1082331
11527003	8210-002	12-Jul-96	1082327	11522011	8210-025	15-Aug-96	1082331
11527004	8210-002	12-Jul-96	1082327	11522012	8210-025	15-Aug-96	1082331
11527005	8210-002	19-Jul-96	1082327	11527042	8210-025	23-Jul-96	1082331
11527006	8210-002	19-Jul-96	1082327	11527043	8210-025	23-Jul-96	1082331
11527007	8210-002	19-Jul-96	1082327	11527044	8210-025	23-Jul-96	1082331
11527008	8210-002	5-Aug-96	1082327	11527045	8210-025	23-Jul-96	1082331
11527009	8210-002	5-Aug-96	1082327	11527046	8210-025	23-Jul-96	1082331
11527010	8210-002	9-Aug-96	1082327	11527047	8210-025	26-Jul-96	1082331
11527011	8210-002	9-Aug-96	1082327	11527048	8210-025	26-Jul-96	1082331
11527012	8210-002	9-Aug-96	1082327	11539568	8210-025	30-Aug-96	1082331
11527013	8210-002	13-Aug-96	1082327	11539569	8210-025	30-Aug-96	1082331
11527014	8210-002	13-Aug-96	1082327	11539570	8210-025	30-Aug-96	1082331
11527015	8210-002	13-Aug-96	1082327	11539571	8210-025	30-Aug-96	1082331
11527016	8210-002	13-Aug-96	1082327	11891104	8210-025	19-Sep-96	1082331
11527017	8210-002	13-Aug-96	1082327	11891105	8210-025	19-Sep-96	1082331
11535061	8210-002	13-Aug-96	1082327	11891106	8210-025	19-Sep-96	1082331
11536530	8210-002	20-Aug-96	1082327	11893462	8210-025	27-Sep-96	1082331
11536531	8210-002	20-Aug-96	1082327	11893463	8210-025	27-Sep-96	1082331
11536532	8210-002	20-Aug-96	1082327	11894054	8210-025	1-Oct-96	1082331
11536533	8210-002	20-Aug-96	1082327	11894055	8210-025	1-Oct-96	1082331
11536534	8210-002	20-Aug-96	1082327	11897436	8210-025	15-Oct-96	1082331

33606



SERVICE BULLETIN

WOODWARD GOVERNOR COMPANY
 AIRCRAFT CONTROLS GROUP
 One Woodward Way
 P.O. Box 405
 Rockton, Illinois 61072-0405
 USA

<u>SERIAL NO.</u>	<u>ITEM NO.</u>	<u>DATE</u>	<u>S/O #</u>	<u>SERIAL NO.</u>	<u>ITEM NO.</u>	<u>DATE</u>	<u>S/O #</u>
11540492	8210-002	5-Sep-96	1082327	11897459	8210-025	15-Oct-96	1082331
11540493	8210-002	5-Sep-96	1082327	11898555	8210-025	21-Oct-96	1082331
11540494	8210-002	5-Sep-96	1082327	11898556	8210-025	21-Oct-96	1082331
11540495	8210-002	5-Sep-96	1082327	11900612	8210-025	25-Oct-96	1082331
11540496	8210-002	5-Sep-96	1082327	11900613	8210-025	25-Oct-96	1082331
11541501	8210-002	10-Sep-96	1082327	11901779	8210-025	30-Oct-96	1082331
11541502	8210-002	10-Sep-96	1082327	11901780	8210-025	30-Oct-96	1082331
11541503	8210-002	10-Sep-96	1082327	11902748	8210-025	1-Nov-96	1082331
11541504	8210-002	10-Sep-96	1082327	11903355	8210-025	5-Nov-96	1082331
11541505	8210-002	2-Jan-97	1153731	11905365	8210-025	12-Nov-96	1082331
11541809	8210-002	10-Sep-96	1082327	11910550	8210-025	26-Nov-96	1082331
11541810	8210-002	10-Sep-96	1082327	11910551	8210-025	26-Nov-96	1082331
11541811	8210-002	10-Sep-96	1082327	11910552	8210-025	26-Nov-96	1082331
11541812	8210-002	10-Sep-96	1082327	11910553	8210-025	18-Dec-96	1149179
11541813	8210-002	10-Sep-96	1082327	11910554	8210-025	18-Dec-96	1149179
11541814	8210-002	10-Sep-96	1082327	11910555	8210-025	18-Dec-96	1149179
11544247	8210-002	17-Sep-96	1082327	11910556	8210-025	18-Dec-96	1149179
11544248	8210-002	17-Sep-96	1082327	11910557	8210-025	18-Dec-96	1149179
11544249	8210-002	17-Sep-96	1082327	11915383	8210-025	18-Dec-96	1149179
11891447	8210-002	26-Sep-96	1082327	11919967	8210-025	6-Jan-97	1152517
11891448	8210-002	26-Sep-96	1082327	11920591	8210-025	13-Jan-97	1152517
11891449	8210-002	26-Sep-96	1082327	11920592	8210-025	13-Jan-97	1152517
11891450	8210-002	26-Sep-96	1082327	11920593	8210-025	13-Jan-97	1152517
11891451	8210-002	26-Sep-96	1082327	11920594	8210-025	17-Jan-97	1152517
11893392	8210-002	27-Sep-96	1135537	11922750	8210-025	17-Jan-97	1152517
11893859	8210-002	30-Sep-96	1082327	11924029	8210-025	22-Jan-97	1152517
11893860	8210-002	30-Sep-96	1082327	11924030	8210-025	22-Jan-97	1152517
11896235	8210-002	16-Oct-96	1082327	11925498	8210-025	30-Jan-97	1152517
11896236	8210-002	16-Oct-96	1082327	11925499	8210-025	30-Jan-97	1152517
11896237	8210-002	16-Oct-96	1082327	11925500	8210-025	30-Jan-97	1152517
11896238	8210-002	16-Oct-96	1082327	11925501	8210-025	30-Jan-97	1152517
11896239	8210-002	16-Oct-96	1082327	11927635	8210-025	6-Feb-97	1152517
11896240	8210-002	23-Jan-97	1156810	11927891	8210-025	7-Feb-97	1152517
11898447	8210-002	18-Oct-96	1082327	11927892	8210-025	7-Feb-97	1152517
11898448	8210-002	18-Oct-96	1082327	11516248	8210-034	23-May-96	1086277
11898449	8210-002	18-Oct-96	1082327	11516248	8210-034	7-Feb-97	1149195
11898450	8210-002	18-Oct-96	1082327	11516249	8210-034	7-Jun-96	1086277
11898451	8210-002	18-Oct-96	1082327	11520276	8210-034	11-Jun-96	1086277
11898452	8210-002	23-Jan-97	1156812	11521959	8210-034	17-Jun-96	1086277
11900624	8210-002	25-Oct-96	1082327	11891603	8210-034	26-Sep-96	1086277
11900625	8210-002	25-Oct-96	1082327	11895775	8210-034	8-Oct-96	1086277
11900626	8210-002	25-Oct-96	1082327	11900910	8210-034	28-Oct-96	1086277
11900627	8210-002	25-Oct-96	1082327	11904292	8210-034	9-Jan-97	1154260
11900628	8210-002	25-Oct-96	1082327	11905115	8210-034	14-Jan-97	1154258
11900877	8210-002	28-Oct-96	1135537	11905116	8210-034	20-Jan-97	1154258
11902327	8210-002	5-Nov-96	1082327	11519117	8210-137	6-Jun-96	1082336
11902328	8210-002	5-Nov-96	1082327	11520593	8210-137	12-Jun-96	1082336

33606



®

SERVICE BULLETIN

WOODWARD GOVERNOR COMPANY
 AIRCRAFT CONTROLS GROUP
 One Woodward Way
 P.O. Box 405
 Rockton, Illinois 61072-0405
 USA

<u>SERIAL NO.</u>	<u>ITEM NO.</u>	<u>DATE</u>	<u>S/O #</u>	<u>SERIAL NO.</u>	<u>ITEM NO.</u>	<u>DATE</u>	<u>S/O #</u>
11902329	8210-002	5-Nov-96	1082327	11520594	8210-137	12-Jun-96	1082336
11902330	8210-002	5-Nov-96	1082327	11521151	8210-137	14-Jun-96	1082336
11902331	8210-002	5-Nov-96	1082327	11522568	8210-137	25-Jul-96	1082336
11902332	8210-002	5-Nov-96	1082327	11533235	8210-137	29-Aug-96	1082336
11902333	8210-002	5-Nov-96	1082327	11533236	8210-137	29-Aug-96	1082336
11902334	8210-002	5-Nov-96	1082327	11533237	8210-137	29-Aug-96	1082336
11902609	8210-002	5-Nov-96	1082327	11538175	8210-137	29-Aug-96	1082336
11902610	8210-002	22-Nov-96	1135537	11538176	8210-137	16-Sep-96	1082336
11902611	8210-002	2-Dec-96	1082327	11892507	8210-137	27-Sep-96	1082336
11903844	8210-002	11-Nov-96	1082327	11893899	8210-137	4-Oct-96	1082336
11903845	8210-002	11-Nov-96	1082327	11893900	8210-137	4-Oct-96	1135549
11903846	8210-002	11-Nov-96	1082327	11897046	8210-137	16-Oct-96	1082336
11903847	8210-002	11-Nov-96	1082327	11897047	8210-137	22-Oct-96	1082336
11903848	8210-002	11-Nov-96	1082327	11900920	8210-137	28-Oct-96	1082336
11903849	8210-002	11-Nov-96	1082327	11903053	8210-137	20-Dec-96	1149176
11903850	8210-002	11-Nov-96	1082327	11904299	8210-137	11-Nov-96	1082336
11903851	8210-002	11-Nov-96	1082327	11904300	8210-137	11-Nov-96	1082336
11903852	8210-002	11-Nov-96	1082327	11915778	8210-137	20-Dec-96	1149176
11903853	8210-002	2-Dec-96	1082327	11922558	8210-137	16-Jan-97	1152430
11903854	8210-002	2-Dec-96	1082327	11922559	8210-137	21-Jan-97	1152430
11910074	8210-002	2-Dec-96	1082327	11924472	8210-137	24-Jan-97	1152430
11910075	8210-002	2-Dec-96	1082327	11927048	8210-137	5-Feb-97	1152430
11910076	8210-002	2-Dec-96	1082327	11927889	8210-137	7-Feb-97	1152430
11910077	8210-002	2-Dec-96	1082327	11507877	8210-212	24-Apr-96	1082354
11910080	8210-002	9-Dec-96	1135537	11508096	8210-212	9-Aug-96	1123878
11910081	8210-002	6-Jan-97	1152452	11508910	8210-212	30-Apr-96	1082354
11910082	8210-002	6-Jan-97	1152452	11508911	8210-212	30-Apr-96	1082354
11910083	8210-002	6-Jan-97	1152452	11509197	8210-212	1-May-96	1082354
11915508	8210-002	30-Dec-96	1149180	11514479	8210-212	20-May-96	1082354
11915509	8210-002	30-Dec-96	1149180	11514480	8210-212	20-May-96	1082354
11915510	8210-002	30-Dec-96	1149180	11515579	8210-212	22-May-96	1082354
11915511	8210-002	30-Dec-96	1149180	11515580	8210-212	22-May-96	1082354
11916558	8210-002	6-Jan-97	1152452	11515581	8210-212	22-May-96	1082354
11919930	8210-002	6-Jan-97	1152452	11515582	8210-212	22-May-96	1082354
11920461	8210-002	8-Jan-97	1152454	11515583	8210-212	22-May-96	1082354
11920462	8210-002	13-Jan-97	1152452	11517541	8210-212	30-May-96	1082354
11920463	8210-002	13-Jan-97	1152452	11517542	8210-212	30-May-96	1082354
11920464	8210-002	13-Jan-97	1152452	11517543	8210-212	16-Oct-96	1139710
11920465	8210-002	13-Jan-97	1152452	11517544	8210-212	26-Jul-96	1082354
11920466	8210-002	17-Jan-97	1152452	11517545	8210-212	23-Oct-96	1141480
11921608	8210-002	17-Jan-97	1152452	11521961	8210-212	24-Jul-96	1082354
11921609	8210-002	17-Jan-97	1152452	11529787	8210-212	24-Jul-96	1082354
11921610	8210-002	17-Jan-97	1152452	11529788	8210-212	24-Jul-96	1082354
11922910	8210-002	17-Jan-97	1152452	11529789	8210-212	24-Jul-96	1082354
11924019	8210-002	22-Jan-97	1152452	11529790	8210-212	24-Jul-96	1082354
11924020	8210-002	22-Jan-97	1152452	11539659	8210-212	30-Aug-96	1082354
11924021	8210-002	22-Jan-97	1152452	11540019	8210-212	4-Sep-96	1082354

33606



SERVICE BULLETIN

WOODWARD GOVERNOR COMPANY
AIRCRAFT CONTROLS GROUP
One Woodward Way
P.O. Box 405
Rockton, Illinois 61072-0405
USA

<u>SERIAL NO.</u>	<u>ITEM NO.</u>	<u>DATE</u>	<u>S/O #</u>	<u>SERIAL NO.</u>	<u>ITEM NO.</u>	<u>DATE</u>	<u>S/O #</u>
11924022	8210-002	22-Jan-97	1152452	11540020	8210-212	4-Sep-96	1082354
11924023	8210-002	22-Jan-97	1152452	11541807	8210-212	10-Sep-96	1082354
11926412	8210-002	4-Feb-97	1152452	11543996	8210-212	16-Sep-96	1082354
11926413	8210-002	4-Feb-97	1152452	11543997	8210-212	16-Sep-96	1082354
11926414	8210-002	4-Feb-97	1152452	11892500	8210-212	26-Sep-96	1082354
11926415	8210-002	4-Feb-97	1152452	11892501	8210-212	26-Sep-96	1082354
11928197	8210-002	10-Feb-97	1152452	11892502	8210-212	26-Sep-96	1082354
11928198	8210-002	10-Feb-97	1152452	11892503	8210-212	26-Sep-96	1082354
11928199	8210-002	10-Feb-97	1152452	11892504	8210-212	26-Sep-96	1135563
11928200	8210-002	10-Feb-97	1152452	11892505	8210-212	4-Oct-96	1082354
11928972	8210-002	12-Feb-97	1152452	11898325	8210-212	18-Oct-96	1082354
11518219	8210-004	4-Jun-96	1094159	11898326	8210-212	18-Oct-96	1082354
11518220	8210-004	4-Jun-96	1094159	11898327	8210-212	18-Oct-96	1082354
11535182	8210-004	18-Nov-96	1094159	11901945	8210-212	30-Oct-96	1082354
11903478	8210-004	18-Nov-96	1094159	11905496	8210-212	12-Nov-96	1082354
11503593	8210-007	4-Apr-96	1082329	11905497	8210-212	12-Nov-96	1082354
11504906	8210-007	11-Apr-96	1082329	11906859	8210-212	19-Nov-96	1141171
11504907	8210-007	11-Apr-96	1082329	11907848	8210-212	4-Dec-96	1082354
11504908	8210-007	11-Apr-96	1082329	11911489	8210-212	4-Dec-96	1082354
11517077	8210-007	29-May-96	1082329	11911490	8210-212	4-Dec-96	1082354
11519120	8210-007	6-Jun-96	1082329	11911491	8210-212	4-Dec-96	1082354
11519121	8210-007	8-Jul-96	1082329	11911492	8210-212	4-Dec-96	1082354
11538107	8210-007	27-Aug-96	1082329	11911493	8210-212	4-Dec-96	1082354
11538108	8210-007	9-Sep-96	1082329	11911494	8210-212	30-Dec-96	1149163
11538109	8210-007	26-Sep-96	1082329	11911495	8210-212	30-Dec-96	1149163
11538110	8210-007	26-Sep-96	1082329	11915740	8210-212	30-Dec-96	1149163
11538111	8210-007	17-Oct-96	1082329	11915741	8210-212	30-Dec-96	1149163
11538112	8210-007	28-Oct-96	1135540	11915742	8210-212	30-Dec-96	1149163
11901968	8210-007	30-Oct-96	1141130	11919141	8210-212	6-Jan-97	1152525
11901969	8210-007	30-Oct-96	1082329	11919142	8210-212	6-Jan-97	1152525
11901970	8210-007	30-Oct-96	1082329	11919143	8210-212	8-Jan-97	1152531
11503642	8210-024	4-Apr-96	1082330	11919144	8210-212	8-Jan-97	1152531
11503643	8210-024	4-Apr-96	1082330	11920614	8210-212	22-Jan-97	1152525
11504486	8210-024	10-Apr-96	1082330	11922667	8210-212	16-Jan-97	1152525
11504487	8210-024	10-Apr-96	1082330	11922668	8210-212	16-Jan-97	1152525
11505904	8210-024	10-Jan-97	1130017	11922669	8210-212	16-Jan-97	1152525
11505905	8210-024	27-Dec-96	1156334	11922670	8210-212	16-Jan-97	1152525
11509158	8210-024	1-May-96	1082330	11925046	8210-212	28-Jan-97	1152525
11509671	8210-024	3-May-96	1082330	11925047	8210-212	28-Jan-97	1152525
11509672	8210-024	3-May-96	1082330	11925048	8210-212	28-Jan-97	1152525
11509673	8210-024	3-May-96	1082330	11925049	8210-212	28-Jan-97	1152525
11513771	8210-024	15-May-96	1082330	11925050	8210-212	28-Jan-97	1152525
11513772	8210-024	15-May-96	1082330	11925051	8210-212	28-Jan-97	1152525
11513773	8210-024	15-May-96	1082330	11925052	8210-212	28-Jan-97	1152525
11513774	8210-024	15-May-96	1082330	11925645	8210-212	30-Jan-97	1152525
11513775	8210-024	15-May-96	1082330	11926631	8210-212	4-Feb-97	1152525
				11926632	8210-212	4-Feb-97	1152525

33606



®

SERVICE BULLETIN

WOODWARD GOVERNOR COMPANY
 AIRCRAFT CONTROLS GROUP
 One Woodward Way
 P.O. Box 405
 Rockton, Illinois 61072-0405
 USA

1. Repair Governors Affected

<u>SERIAL NO.</u>	<u>ITEM NO.</u>	<u>DATE</u>	<u>S/O #</u>	<u>SERIAL NO.</u>	<u>ITEM NO.</u>	<u>DATE</u>	<u>S/O #</u>
989554	8210-002	23-Sep-96	1137947	1150541	8210-006	26-Nov-96	1145888
989690	8210-002	20-Sep-96	1137590	1107913	8210-007	4-Dec-96	1152272
989788	8210-002	1-Oct-96	1134506	1107970	8210-007	22-Nov-96	1149564
1150374	8210-002	13-Sep-96	1120639	1107985	8210-007	3-Jul-96	1122016
1190056	8210-002	20-Sep-96	1136452	1150465	8210-007	11-Nov-96	1147226
1199173	8210-002	28-Aug-96	1131341	1150482	8210-007	25-Sep-96	1138305
1201085	8210-002	30-Sep-96	1134506	1156072	8210-007	26-Nov-96	1149563
1206401	8210-002	9-Jan-97	1158228	1201034	8210-007	18-Oct-96	1143333
1284735	8210-002	8-Nov-96	1146917	1208914	8210-007	11-Oct-96	1141489
1284822	8210-002	7-Jun-96	1116159	1298500	8210-007	30-Aug-96	1129486
1284849	8210-002	27-Jun-96	1120516	1451527	8210-007	18-Oct-96	1142436
1284857	8210-002	24-May-96	1113386	1451544	8210-007	23-Oct-96	1142662
1284869	8210-002	22-Nov-96	1150420	1452513	8210-007	25-Sep-96	1138306
1284890	8210-002	15-Oct-96	1142487	1573953	8210-007	6-Nov-96	1146929
1435625	8210-002	3-Oct-96	1120635	1573986	8210-007	16-Jan-97	1159975
1435678	8210-002	14-Aug-96	1128781	1574074	8210-007	10-Feb-97	1164309
1451947	8210-002	10-Sep-96	1134645	1574088	8210-007	17-Jun-96	1110328
1452041	8210-002	17-Oct-96	1142433	1577291	8210-007	4-Jun-96	1115582
1452043	8210-002	3-Dec-96	1151125	1577407	8210-007	16-Oct-96	1141759
1476476	8210-002	10-May-96	1111084	1577416	8210-007	17-Jul-96	1102441
1480073	8210-002	23-Sep-96	1137834	1587442	8210-007	25-Jul-96	1121906
1480157	8210-002	11-Oct-96	1141493	1703590	8210-007	29-May-96	1115073
1485468	8210-002	17-Jan-97	1159885	1703705	8210-007	10-Feb-97	1164326
1485503	8210-002	27-Nov-96	1134504	1703720	8210-007	18-Oct-96	1142880
1485656	8210-002	20-Dec-96	1155905	1703793	8210-007	22-Nov-96	1150092
1567708	8210-002	20-Dec-96	1155905	1744272	8210-007	22-Nov-96	1150091
1568331	8210-002	1-Oct-96	1134506	1744312	8210-007	18-Jul-96	1120404
1569677	8210-002	16-Aug-96	1129186	1744389	8210-007	27-Dec-96	1156257
1577897	8210-002	3-Dec-96	1152456	1745025	8210-007	27-Nov-96	1144969
1577953	8210-002	28-Jan-97	1162405	1755691	8210-007	8-Aug-96	1129663
1580061	8210-002	27-Dec-96	1156869	1755765	8210-007	10-Feb-97	1164159
1580065	8210-002	22-Aug-96	1131581	1758720	8210-007	11-Jul-96	1101018
1580105	8210-002	6-Nov-96	1145959	1814485	8210-007	3-Feb-97	1163549
1580110	8210-002	6-Nov-96	1145958	1993872	8210-007	15-Aug-96	1129282
1580136	8210-002	7-Aug-96	1129353	1998063	8210-007	10-Feb-97	1164307
1580145	8210-002	19-Nov-96	1149517	2007831	8210-007	20-Aug-96	1117300
1580308	8210-002	21-Oct-96	1143788	2128979	8210-007	11-Nov-96	1148230
1580323	8210-002	18-Oct-96	1142877	2131577	8210-007	10-Dec-96	1149441
1580439	8210-002	20-Aug-96	1130090	2133728	8210-007	20-Jan-97	1149445
1586069	8210-002	31-Dec-96	1156737	2135145	8210-007	27-Dec-96	1156061
1702643	8210-002	21-Sep-96	1138089	2138094	8210-007	14-Aug-96	1129194
1704429	8210-002	27-Nov-96	1134504	2171243	8210-007	11-Oct-96	1139845
1704642	8210-002	31-Dec-96	1156744	2240711	8210-007	16-Sep-96	1136855

33606

Page 10 of 14
 Feb 21/97



®

SERVICE BULLETIN

WOODWARD GOVERNOR COMPANY
AIRCRAFT CONTROLS GROUP
One Woodward Way
P.O. Box 405
Rockton, Illinois 61072-0405
USA

<u>SERIAL NO.</u>	<u>ITEM NO.</u>	<u>DATE</u>	<u>S/O #</u>	<u>SERIAL NO.</u>	<u>ITEM NO.</u>	<u>DATE</u>	<u>S/O #</u>
1704663	8210-002	27-Nov-96	1134504	2241474	8210-007	2-Dec-96	1149455
1704664	8210-002	11-Dec-96	1153662	2242910	8210-007	18-Oct-96	1142470
1704683	8210-002	7-May-96	1110705	2245862	8210-007	29-Oct-96	1141969
1704706	8210-002	8-May-96	1110806	2254977	8210-007	18-Nov-96	1149460
1704714	8210-002	20-Aug-96	1130729	2345156	8210-007	1-Jul-96	1117065
1704748	8210-002	3-Sep-96	1120639	2345285	8210-007	4-Sep-96	1133718
1704758	8210-002	24-Jan-97	1161591	2345680	8210-007	7-Aug-96	1124652
1704896	8210-002	23-Oct-96	1143658	2453419	8210-007	9-Oct-96	1140912
1715779	8210-002	7-Jan-97	1155903	11542079	8210-007	2-Oct-96	1135519
1715796	8210-002	20-Aug-96	1130730	1715077	8210-024	20-Jan-97	1158687
1720027	8210-002	14-Jan-97	1158436	1715093	8210-024	13-May-96	1111733
1744933	8210-002	10-May-96	1111273	1715126	8210-024	20-Jan-97	1158689
1747318	8210-002	3-Oct-96	1120633	1715130	8210-024	7-Nov-96	1146819
1754191	8210-002	11-Nov-96	1147723	1715197	8210-024	12-Nov-96	1147555
1754214	8210-002	8-Nov-96	1146926	1715392	8210-024	11-Dec-96	1150853
1754282	8210-002	10-Feb-97	1163598	1747719	8210-024	22-May-96	1112429
1754801	8210-002	6-Jan-97	1157229	1807091	8210-024	6-Nov-96	1146820
1755247	8210-002	4-Sep-96	1133031	1807224	8210-024	6-May-96	1110983
1755429	8210-002	10-Jan-97	1158446	1807226	8210-024	15-Nov-96	1147954
1758533	8210-002	22-Aug-96	1131010	1807227	8210-024	3-May-96	1110562
1759573	8210-002	22-Nov-96	1150143	1807247	8210-024	7-May-96	1111082
1760290	8210-002	26-Jun-96	1119539	1807261	8210-024	14-Jan-97	1158225
1992519	8210-002	13-Jan-97	1158802	1807264	8210-024	3-Oct-96	1139860
1995739	8210-002	1-Jul-96	1121505	1807274	8210-024	12-Dec-96	1153341
1995901	8210-002	29-Oct-96	1144967	1807278	8210-024	16-Sep-96	1135192
1997580	8210-002	26-Aug-96	1131579	1807281	8210-024	15-Jan-97	1158798
1998047	8210-002	19-Aug-96	1131390	1818433	8210-024	25-Oct-96	1143570
2002426	8210-002	2-May-96	1110565	1818444	8210-024	25-Oct-96	1143569
2003074	8210-002	15-Jan-97	1159248	1818529	8210-024	6-Aug-96	1127018
2003596	8210-002	13-Sep-96	1120639	1818539	8210-024	3-May-96	1110564
2003620	8210-002	28-May-96	1114056	1818549	8210-024	4-Nov-96	1146160
2120643	8210-002	27-Jun-96	1120834	1818592	8210-024	15-Jan-97	1159022
2120675	8210-002	27-Nov-96	1150854	1818642	8210-024	19-Dec-96	1155468
2122918	8210-002	15-Aug-96	1130135	1818665	8210-024	20-Jan-97	1158686
2127042	8210-002	22-Aug-96	1131340	2126035	8210-024	20-Jan-97	1158684
2127225	8210-002	9-Dec-96	1151894	2136019	8210-024	7-Feb-97	1163135
2131526	8210-002	13-Sep-96	1120639	2174640	8210-024	12-Aug-96	1128488
2135311	8210-002	24-Sep-96	1137833	2240952	8210-024	19-Dec-96	1154472
2137986	8210-002	28-Oct-96	1134502	2241181	8210-024	20-Dec-96	1155512
2138061	8210-002	28-Oct-96	1144680	2252037	8210-024	4-Nov-96	1146158
2138089	8210-002	17-Oct-96	1141973	2345085	8210-024	13-May-96	1111734
2138102	8210-002	28-Oct-96	1134502	2347662	8210-024	30-Apr-96	1107140
2138125	8210-002	3-Jan-97	1157658	2476896	8210-024	31-Jan-97	1162215
2170674	8210-002	16-Aug-96	1129189	1701086	8210-025	12-Aug-96	1127372
2170698	8210-002	31-Oct-96	1146051	1701178	8210-025	1-Aug-96	1126594
2170701	8210-002	13-Nov-96	1146920	1746547	8210-025	6-Jan-97	1157095
2171489	8210-002	9-Jan-97	1157895	1746573	8210-025	22-Nov-96	1150141

33606



®

SERVICE BULLETIN

WOODWARD GOVERNOR COMPANY
 AIRCRAFT CONTROLS GROUP
 One Woodward Way
 P.O. Box 405
 Rockton, Illinois 61072-0405
 USA

<u>SERIAL NO.</u>	<u>ITEM NO.</u>	<u>DATE</u>	<u>S/O #</u>	<u>SERIAL NO.</u>	<u>ITEM NO.</u>	<u>DATE</u>	<u>S/O #</u>
2172801	8210-002	21-Oct-96	1143788	1746574	8210-025	7-Oct-96	1140707
2173983	8210-002	20-Sep-96	1137591	1746718	8210-025	22-May-96	1113198
2173992	8210-002	28-Oct-96	1134502	1746798	8210-025	4-Nov-96	1146161
2175092	8210-002	2-May-96	1106860	1749673	8210-025	19-Jun-96	1117311
2175103	8210-002	13-Sep-96	1120639	1749785	8210-025	21-Jan-97	1159968
2241215	8210-002	8-Nov-96	1147561	1749787	8210-025	23-Jan-97	1159967
2241231	8210-002	28-Oct-96	1134502	1749800	8210-025	17-Jan-97	1159885
2241277	8210-002	28-Oct-96	1134502	1749818	8210-025	10-May-96	1110804
2241286	8210-002	27-Dec-96	1156869	1749997	8210-025	30-Jul-96	1126232
2243362	8210-002	27-Nov-96	1134504	1814918	8210-025	29-Jul-96	1126231
2244540	8210-002	16-May-96	1112861	1815013	8210-025	7-Aug-96	1128669
2244557	8210-002	4-Nov-96	1146712	1815042	8210-025	30-May-96	1116509
2246668	8210-002	14-Jun-96	1117928	1815048	8210-025	6-Nov-96	1146808
2247345	8210-002	24-Oct-96	1144151	1815059	8210-025	4-Dec-96	1152246
2248082	8210-002	29-Jun-96	1121504	1815153	8210-025	14-May-96	1110325
2251734	8210-002	1-Oct-96	1134506	1815190	8210-025	5-Dec-96	1152595
2256187	8210-002	7-May-96	1107134	1815216	8210-025	22-Aug-96	1131585
2326152	8210-002	27-Nov-96	1134504	1815285	8210-025	7-Aug-96	1128669
2340289	8210-002	18-Oct-96	1142876	1815288	8210-025	19-Nov-96	1149518
2344289	8210-002	10-Sep-96	1132054	2242205	8210-025	4-Nov-96	1146165
2345404	8210-002	16-Sep-96	1116050	2248358	8210-025	17-Jan-97	1159885
2345905	8210-002	21-Sep-96	1137587	2331132	8210-025	18-Oct-96	1143662
2347099	8210-002	31-Dec-96	1156750	2345340	8210-025	23-Aug-96	1132053
2347463	8210-002	12-Sep-96	1116051	2346448	8210-025	25-Sep-96	1138307
2453702	8210-002	18-Jul-96	1123971	2455738	8210-025	11-Nov-96	1146718
2454925	8210-002	24-Oct-96	1144153	2490875	8210-025	12-Nov-96	1147232
2455270	8210-002	28-Oct-96	1144678	2491246	8210-025	20-Sep-96	1137592
2477754	8210-002	15-Jul-96	1095533	1701061	8210-027	16-Dec-96	1153591
2478780	8210-002	24-Oct-96	1144149	1701124	8210-027	8-Nov-96	1147266
2481652	8210-002	1-Nov-96	1144972	1701159	8210-027	9-Aug-96	1129872
2482386	8210-002	7-Jan-97	1156068	1818813	8210-027	25-Jun-96	1112346
2485100	8210-002	30-Sep-96	1134506	2172799	8210-027	8-Nov-96	1147264
2488210	8210-002	12-Nov-96	1142486	2249118	8210-027	16-Dec-96	1153590
2490378	8210-002	22-Nov-96	1150421	2344716	8210-027	7-Jan-97	1158136
10020138	8210-002	30-Oct-96	1143257	2454166	8210-027	4-Nov-96	1143869
11394000	8210-002	11-Oct-96	1131842	1528077	8210-034	22-Jan-97	1160747
11462579	8210-002	15-Aug-96	1130137	1720161	8210-034	6-Jan-97	1157093
11542291	8210-002	3-Oct-96	1139855	1720165	8210-034	11-Jul-96	1122210
11542292	8210-002	4-Oct-96	1140906	1991652	8210-034	30-May-96	1108689
11542293	8210-002	30-Oct-96	1145338	2128095	8210-034	1-Aug-96	1126496
11542294	8210-002	12-Dec-96	1154446	2135487	8210-034	17-Sep-96	1133827
11542295	8210-002	7-Oct-96	1141005	2137850	8210-034	10-Feb-97	1164750
11910078	8210-002	12-Dec-96	1154446	2169970	8210-034	18-Nov-96	1149461
1109066	8210-003	8-Nov-96	1146916	2242679	8210-034	24-Sep-96	1137901
1145378	8210-003	6-Dec-96	1152533	2244887	8210-034	29-Aug-96	1129490
1148581	8210-003	9-Jan-97	1158623	2248319	8210-034	29-Aug-96	1130393
1190015	8210-003	4-Oct-96	1139842	2253872	8210-034	30-Dec-96	1154853

33606

Page 12 of 14
 Feb 21/97



SERVICE BULLETIN

WOODWARD GOVERNOR COMPANY
 AIRCRAFT CONTROLS GROUP
 One Woodward Way
 P.O. Box 405
 Rockton, Illinois 61072-0405
 USA

<u>SERIAL NO.</u>	<u>ITEM NO.</u>	<u>DATE</u>	<u>S/O #</u>	<u>SERIAL NO.</u>	<u>ITEM NO.</u>	<u>DATE</u>	<u>S/O #</u>
1198336	8210-003	18-Nov-96	1149458	2330218	8210-034	19-Sep-96	1135698
1200808	8210-003	7-Aug-96	1129437	2331102	8210-034	5-Aug-96	1127803
1298463	8210-003	5-Dec-96	1152595	2454078	8210-034	4-Nov-96	1146156
1435419	8210-003	15-Jul-96	1123056	2456488	8210-034	16-Jul-96	1123224
1442103	8210-003	29-May-96	1114719	2456488	8210-034	3-Feb-97	1160770
1451925	8210-003	17-Jul-96	1122246	2456581	8210-034	20-May-96	1113067
1480169	8210-003	23-Jul-96	1124208	2456583	8210-034	10-Sep-96	1128618
1485518	8210-003	28-May-96	1114710	2002281	8210-133	9-Oct-96	1140913
1485640	8210-003	13-Nov-96	1148123	11501328	8210-137	25-Mar-96	1097361
1495613	8210-003	1-Oct-96	1138438	11513656	8210-137	17-May-96	1097361
1495622	8210-003	11-Feb-97	1164554	11513819	8210-137	25-Oct-96	1145002
1495642	8210-003	2-Jul-96	1121759	1988283	8210-209	3-Feb-97	1162705
1568219	8210-003	23-Jul-96	1124207	1988286	8210-209	12-Aug-96	1128330
1573711	8210-003	2-Jul-96	1121758	1988289	8210-209	17-Jan-97	1159030
1580190	8210-003	26-Nov-96	1150948	2001455	8210-209	9-Jul-96	1122223
1580286	8210-003	30-Jul-96	1126511	2119642	8210-209	6-Jun-96	1110324
1586130	8210-003	28-Jun-96	1120935	2456632	8210-209	23-Jul-96	1124678
1586880	8210-003	2-Dec-96	1151103	1808994	8210-212	3-Jan-97	1157853
1704005	8210-003	15-Aug-96	1129470	1986641	8210-212	31-Jul-96	1126592
1704091	8210-003	16-Jul-96	1124905	1986695	8210-212	25-Jul-96	1121363
1704194	8210-003	22-Aug-96	1131584	1986722	8210-212	30-Aug-96	1133565
1704725	8210-003	8-Jan-97	1157407	1986731	8210-212	31-Dec-96	1156365
1818422	8210-003	10-Jul-96	1122478	1986734	8210-212	21-Oct-96	1142789
1827160	8210-003	30-Jul-96	1126505	1986758	8210-212	6-Feb-97	1164597
2002071	8210-003	12-Dec-96	1153313	1986767	8210-212	28-May-96	1114203
2004363	8210-003	25-Oct-96	1143845	1986781	8210-212	16-Jul-96	1101016
2004515	8210-003	3-Jul-96	1122006	1986820	8210-212	9-Oct-96	1140962
2120433	8210-003	28-May-96	1111279	1992659	8210-212	7-Oct-96	1140406
2133564	8210-003	10-Jul-96	1122483	1992708	8210-212	13-Dec-96	1153348
2137752	8210-003	16-Aug-96	1127364	1992721	8210-212	15-Jan-97	1159517
2170789	8210-003	17-Jul-96	1122236	1992744	8210-212	23-Sep-96	1137835
2242923	8210-003	21-Jan-97	1155808	1992748	8210-212	13-Dec-96	1153347
2253640	8210-003	29-Jul-96	1126500	1992898	8210-212	6-Nov-96	1146925
2257228	8210-003	22-Aug-96	1132057	2119802	8210-212	18-Dec-96	1152280
2257229	8210-003	30-Sep-96	1133227	2134088	8210-212	1-Aug-96	1126499
2346192	8210-003	24-Apr-96	1109169	2137236	8210-212	5-Dec-96	1152595
2453716	8210-003	9-Dec-96	1153351	2137310	8210-212	13-Nov-96	1147599
11491631	8210-003	27-Nov-96	1151570	2166439	8210-212	6-Nov-96	1146923
11541837	8210-003	11-Sep-96	1122065	2166441	8210-212	11-Oct-96	1141485
1151686	8210-004	20-May-96	1112858	2166461	8210-212	14-Aug-96	1128486
1151922	8210-004	29-May-96	1114714	2166465	8210-212	7-Aug-96	1128159
1156112	8210-004	29-Aug-96	1128326	2169892	8210-212	8-Nov-96	1147563
1192734	8210-004	11-Jul-96	1120928	2169909	8210-212	19-Aug-96	1130100
1198026	8210-004	18-Sep-96	1135806	2170039	8210-212	4-Feb-97	1161877
1200180	8210-004	26-Mar-96	1104110	2174049	8210-212	2-Jul-96	1121377
1208341	8210-004	31-Oct-96	1144644	2174053	8210-212	22-Oct-96	1142900
1447715	8210-004	2-Jul-96	1121506	2242049	8210-212	7-Jan-97	1157237

33606



®

SERVICE BULLETIN

WOODWARD GOVERNOR COMPANY
AIRCRAFT CONTROLS GROUP
One Woodward Way
P.O. Box 405
Rockton, Illinois 61072-0405
USA

<u>SERIAL NO.</u>	<u>ITEM NO.</u>	<u>DATE</u>	<u>S/O #</u>	<u>SERIAL NO.</u>	<u>ITEM NO.</u>	<u>DATE</u>	<u>S/O #</u>
1451302	8210-004	13-Jun-96	1117015	2243430	8210-212	22-Oct-96	1143548
1480184	8210-004	10-May-96	1111083	2245856	8210-212	25-Nov-96	1150664
1569694	8210-004	17-Jun-96	1116721	2246000	8210-212	20-Dec-96	1156273
1577195	8210-004	31-Dec-96	1156466	2246001	8210-212	2-Dec-96	1151699
1586226	8210-004	5-Feb-97	1164223	2248090	8210-212	30-Dec-96	1153772
1704383	8210-004	17-Oct-96	1142272	2250472	8210-212	9-Jan-97	1157491
1706608	8210-004	8-Jan-97	1157445	2250497	8210-212	17-Oct-96	1141972
1710136	8210-004	8-Aug-96	1128610	2250518	8210-212	12-Sep-96	1134462
1714650	8210-004	23-Jul-96	1124134	2250522	8210-212	30-Sep-96	1137848
1714653	8210-004	12-Nov-96	1143932	2250549	8210-212	10-Dec-96	1132780
1716838	8210-004	25-Jul-96	1125845	2254223	8210-212	16-Sep-96	1134755
1745975	8210-004	3-Jul-96	1121189	2254234	8210-212	14-Jan-97	1157489
1761246	8210-004	20-Jun-96	1118903	2254250	8210-212	17-Oct-96	1141987
1825230	8210-004	23-May-96	1074299	2254258	8210-212	3-Jul-96	1121376
1986874	8210-004	15-Aug-96	1129206	2254268	8210-212	18-Nov-96	1149456
1995337	8210-004	24-Jul-96	1123961	2328405	8210-212	23-Jan-97	1155540
1997579	8210-004	9-Jul-96	1113910	2328406	8210-212	17-Oct-96	1142440
2004878	8210-004	8-Oct-96	1139521	2329806	8210-212	12-Aug-96	1128484
2007166	8210-004	23-May-96	1074263	2346236	8210-212	2-Dec-96	1151692
2126040	8210-004	26-Nov-96	1147227	2346602	8210-212	2-Oct-96	1139246
2175064	8210-004	14-May-96	1100694	2346667	8210-212	18-Sep-96	1135685
2247867	8210-004	22-May-96	1111631	2346980	8210-212	28-Jun-96	1120960
2253425	8210-004	13-May-96	1111826	2454176	8210-212	25-Jun-96	1115891
2255379	8210-004	20-Jun-96	1118994	2455282	8210-212	22-Oct-96	1142468
2330170	8210-004	19-Jun-96	1116698	2455309	8210-212	16-Jan-97	1159018
2344928	8210-004	29-May-96	1113327	2455806	8210-212	18-Nov-96	1149452
2345812	8210-004	29-Oct-96	1144434	2456504	8210-212	25-Jun-96	1117350
2345850	8210-004	2-Dec-96	1146957	2457009	8210-212	9-Oct-96	1140960
2347137	8210-004	23-Sep-96	1137441	2476613	8210-212	15-Oct-96	1141753
2347200	8210-004	18-Oct-96	1141719	2477171	8210-212	16-Jan-97	1159023
2347203	8210-004	24-Jul-96	1124919	2477691	8210-212	11-Nov-96	1147883
2347455	8210-004	18-Dec-96	1153618	2489999	8210-212	30-Aug-96	1133565
2347505	8210-004	9-Jul-96	1122228	11491941	8210-212	31-Jul-96	1126600
2479200	8210-004	25-Nov-96	1149267				

33606

Page 14 of 14
Feb 21/97