



PILATUS AIRCRAFT LTD. CH-6371 STANS, SWITZERLAND

# SERVICE LETTER

**SUBJECT: PPG INDUSTRIES SERVICE INFORMATION LETTER NO: 172121-001**

To all Customers:

Date: Sep 24/98

This Service Letter is issued to draw the attention of all customers to the following vendor information:

**PPG Service Information Letter No: 172121-001 - Repair of De-bonded Outboard Fiberglass Strap on Glass Windshields (Dated Jan 14/98).**

Pilatus recommends the incorporation of this SIL, as a recommended repair procedure, for all PC-12 and PC-12/45 aircraft.

If you have not received this document - direct from the vendor, please contact them at the address given below:

PPG Industries, Inc.  
Aircraft Products  
Huntsvill, Al. USA.

If you require further information on the subject, please contact Pilatus at the address given below:

PILATUS AIRCRAFT LTD.  
CUSTOMER LIAISON MANAGER,  
CH-6371 STANS, Tel: + 41 41 619 6319  
SWITZERLAND. Fax: + 41 41 610 3351

