## **SERVICE LETTER**

SUBJECT: HONEYWELL SERVICE MEMO 380

To all Customers and Operators: Date: Sep 24/05

This Service Letter is issued to draw attention to the following vendor information:

## **HONEYWELL SERVICE MEMO 380**

Honeywell Service Memo 380 gives information on the position Honeywell will now take with regard to the compliance dates in the service literature that they publish.

Pilatus recommends operators read the Honeywell Service Memo 380. They must understand that if Honeywell have offered to pay for the work necessary to have the changes incorporated and they do not take the necessary actions before the compliance date, Honeywell will not now pay for the work.

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD., CUSTOMER SUPPORT MANAGER, CH-6371 STANS, SWITZERLAND.

General Aviation Tel: + 41 41 619 6208 Fax: + 41 41 619 7311 eMail: SupportPC12@pilatus-aircraft.com

Government Tel: + 41 41 619 6509

Tel: + 41 41 619 6509 Fax: + 41 41 619 6224

eMail: rpaterson@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD., PRODUCT SUPPORT DEPARTMENT, 11755 AIRPORT WAY, BROOMFIELD, CO 80021.

Tel: 303 465 9099 Fax: 303 465 6040

eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD., 17 James Schofield Drive, Adelaide Airport SA 5950, AUSTRALIA

Tel: +61 (08) 8234 4433 Fax: +61 (08) 8234 4499 Free Call: 1800 445 007 eMail: info@pilatus.com.au



INTENTIONALLY BLANK