

# SERVICE LETTER

## **SUBJECT: NEW MAP-LIGHT SWITCH ASSEMBLY**

To all Customers and Operators:

Date: Sep 18/06

This Service Letter is issued to draw attention to the following information:

### **New Map-Light Switch Assembly (P/N 527.10.12.310)**

The map light switch (P/N 944.30.19.331) installed on the earlier aircraft has been superseded. The map light switch (P/N 944.30.19.333) installed on the later aircraft cannot be installed as a direct replacement for the earlier switch because of the difference in external diameters.

The map light switch (P/N 944.30.19.331) has an external diameter of approximately 12 mm (0.472 in.). The map light switch (P/N 944.30.19.333) has an external diameter of 15.824 mm (0.623 in.).

Pilatus have found another supplier who can provide a similar switch (P/N 944.30.19.334) but with a smaller external diameter. This map light switch assembly (P/N 527.10.12.310) has two parts, a switch bearing and a switch as shown in the Illustrated Parts Catalog (Ref. 27-10-00, Fig 03).

The switch bearing (P/N 527.10.12.311), which is bonded into the yoke, has an external diameter of approximately 12 mm (0.472 in.) and a 10 mm threaded internal diameter. The switch has a 10 mm threaded external diameter.

Customers and Operators who have the map light switch (P/N 944.30.19.331) installed and need to replace it, must order a map-light switch assembly (P/N 527.10.12.310), thereafter, they only need to order the switch (P/N 944.30.19.334).

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD.,  
CUSTOMER SUPPORT MANAGER,  
CH-6371 STANS,  
SWITZERLAND.

General Aviation  
Tel : + 41 41 619 6208  
Fax: + 41 41 619 7311  
eMail: SupportPC12@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,  
PRODUCT SUPPORT DEPARTMENT,  
11755 AIRPORT WAY,  
BROOMFIELD, CO 80021.  
USA

Tel : 303 465 9099  
Fax: 303 465 6040  
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD.,  
17 James Schofield Drive,  
Adelaide Airport SA 5950,  
AUSTRALIA

Tel : +61 (08) 8234 4433  
Fax: +61 (08) 8234 4499  
Free Call: 1800 445 007  
eMail: info@pilatus.com.au