



PILATUS AIRCRAFT LTD. CH-6371 STANS, SWITZERLAND

# SERVICE LETTER

**SUBJECT: CHANGE TO HYDRAULIC FLUID**

To all Customers, Operators and Maintenance Units:

Date: Jan 22/07

This Service Letter is issued to draw attention to the following information:

## **CHANGE TO HYDRAULIC FLUID**

The hydraulic fluid currently used on the PC-12 is Castrol Aero 585B (MIL-H-5606), Material Number P10-003 (Pilatus P/N 908.14.12.015).

This hydraulic fluid is obsolete.

Pilatus has replaced Castrol Aero 585B with Aeroshell Fluid 41 (MIL-PRF-5606), Material No. P10-017 (Pilatus P/N 908.14.12.017).

This Service Letter is issued to advise all Customers, Operators and Maintenance Units of the change in hydraulic fluid. Furthermore, the two types of hydraulic fluids can be mixed.

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD.,  
CUSTOMER SUPPORT MANAGER,  
CH-6371 STANS,  
SWITZERLAND.

General Aviation  
Tel : + 41 41 619 6208  
Fax: + 41 41 619 7311  
eMail: SupportPC12@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,  
PRODUCT SUPPORT DEPARTMENT,  
11755 AIRPORT WAY,  
BROOMFIELD, CO 80021.  
USA

Tel : 303 465 9099  
Fax: 303 465 6040  
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD.,  
17 James Schofield Drive,  
Adelaide Airport SA 5950,  
AUSTRALIA

Tel : +61 (08) 8234 4433  
Fax: +61 (08) 8234 4499  
Free Call: 1800 445 007  
eMail: info@pilatus.com.au