

SERVICE LETTER

SUBJECT: L-3 COMMUNICATIONS AVIONICS SYSTEMS - SERVICE LETTER (SL) 10 (REV. M)

To all Customers, Operators and Service Centers:

Date: Dec 03/08

This Service Letter is issued to draw attention to the following vendor information:

GYRO HANDLING, STORAGE AND PACKAGING

L-3 Communications have issued SL-10 (Rev. M) to provide all service centers and opperators information concerning gyro handling, storage, packaging and shipping.

The SL advises that electro-mechanical gyros are extremely delicate instruments and can be easily damaged by incorrect handling.

Pilatus recommends service centers and operators to read L-3 Communications SL-10 (Rev. M) to prevent damage to flight instruments which use electro-mechanical gyros.

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD., CUSTOMER SUPPORT MANAGER, CH-6371 STANS, SWITZERLAND.

General Aviation Tel: + 41 41 619 6208 Fax: + 41 41 619 7311 eMail: SupportPC12@pilatus-aircraft.com

Government

Tel: + 41 41 619 6226 Fax: + 41 41 619 6170

eMail: snolan@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD., PRODUCT SUPPORT DEPARTMENT, 11755 AIRPORT WAY, BROOMFIELD, CO 80021. USA

Tel: 303 465 9099 Fax: 303 465 6040

eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD., 17 James Schofield Drive, Adelaide Airport SA 5950, AUSTRALIA

Tel: +61 (08) 8234 4433 Fax: +61 (08) 8234 4499 Free Call: 1800 445 007 eMail: info@pilatus.com.au

Attachments: L-3 COMMUNICATIONS AVIONICS SYSTEMS SL-10 (REV. M)



INTENTIONALLY BLANK

SERVICE LETTER 128
PAGE 2 of 2