



PILATUS AIRCRAFT LTD. CH-6371 STANS, SWITZERLAND

SERVICE LETTER

SUBJECT: PC-12/47E RIGHT-HAND POWER JUNCTION BOX - INTRODUCTION OF NEW PART NUMBER

To all Customers, Operators and Service Centers:

Date: Jan 12/09

Effective from MSN 1121, the Right-Hand Power Junction Box (RHPJB) will be installed with a circuit breaker for the Foot Warmer option. In cases where the aircraft is not equipped with this option, the circuit breaker will have a lockout ring installed and an inoperative (INOP) sticker.

The new RHPJB is Pilatus Part Number 974.03.38.140 (Manufacturer Part Number FE1549R-01).

The old RHPJB, Pilatus Part Number 974.03.38.137, installed on aircraft MSN 1001 to 1120 is now superseded and will be replaced on attrition with the new RHPJB.

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD.,
CUSTOMER SUPPORT MANAGER,
CH-6371 STANS,
SWITZERLAND.

General Aviation
Tel : + 41 41 619 6208
Fax: + 41 41 619 7311
eMail: SupportPC12@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,
PRODUCT SUPPORT DEPARTMENT,
11755 AIRPORT WAY,
BROOMFIELD, CO 80021.
USA

Tel : 303 465 9099
Fax: 303 465 6040
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD.,
17 James Schofield Drive,
Adelaide Airport SA 5950,
AUSTRALIA

Tel : +61 (08) 8234 4433
Fax: +61 (08) 8234 4499
Free Call: 1800 445 007
eMail: info@pilatus.com.au

≡PILATUS≡
PC12
SERVICE LETTER

INTENTIONALLY BLANK