

**SUBJECT: PC-12/47E SERIES AIRCRAFT - RIGHT HAND POWER JUNCTION BOX - INTRODUCTION OF A NEW PART NUMBER**

To all Customers, Operators and Service Centers:

Date: Aug 19/10

This Service Letter is issued to draw attention to the following information:

Effective from MSN 1263, the Right Hand Power Junction Box (RHPJB) will incorporate a modified cabin bus relay designed to better handle the electrical loads associated with the Cabin Bus.

The new RHPJB is Pilatus Part Number 974.03.38.143 (Manufacturer's Part Number FE1549R-02).

The current RHPJB, Pilatus Part Number 974.03.38.140 (standard installation from aircraft MSN 1121 and up on production) is now superseded and will be replaced on attrition with the new RHPJB.

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD.,  
CUSTOMER SUPPORT MANAGER,  
CH-6371 STANS,  
SWITZERLAND.

General Aviation  
Tel : + 41 41 619 3333  
Fax: + 41 41 619 7311  
eMail: SupportPC12@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,  
PRODUCT SUPPORT DEPARTMENT,  
11755 AIRPORT WAY,  
BROOMFIELD, CO 80021.  
USA

Tel : 303 465 9099  
Fax: 303 465 6040  
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD.,  
17 James Schofield Drive,  
Adelaide Airport SA 5950,  
AUSTRALIA

Tel : +61 (08) 8234 4433  
Fax: +61 (08) 8234 4499  
Free Call: 1800 445 007  
eMail: SupportPC12@pilatus.com.au

**Attachments: None**

INTENTIONALLY BLANK