

**SUBJECT: FILTER ELEMENT INCORRECT MARKING**

Date: May 21/14

To all Customers, Operators and Service Centers:

Applicability: All PC-12 Series Aircraft

This Service Letter is issued to draw attention to Pratt & Whitney Canada Service Information Letter SILPT6A-218 (latest revision).

Pratt & Whitney Canada have identified a number of non-cleanable filter elements P/N 3059778-01 that are incorrectly marked with the interchangeability P/N 3059779-01.

Pilatus recommends that customers follow the advice given in P&WC SIL PT6A-218 (latest revision) for affected lot numbers.

Operators who require further information should contact their Customer Liaison Manager at one of the following addresses given below:

PILATUS AIRCRAFT LTD.  
CUSTOMER SUPPORT MANAGER  
CH-6371 STANS  
SWITZERLAND  
General Aviation  
Tel: +41 41 619 3333  
Fax: +41 41 619 7311  
eMail: SupportPC12@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.  
PRODUCT SUPPORT DEPARTMENT  
11755 AIRPORT WAY  
BROOMFIELD, CO 80021  
UNITED STATES OF AMERICA  
Tel: +1 303 465 9099  
Fax: +1 303 465 6040  
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA PTY LTD.  
17 JAMES SCHOFIELD DRIVE  
ADELAIDE AIRPORT SA 5950  
AUSTRALIA  
Tel: +61 8 8238 1600  
Fax: +61 8 8234 4499  
Free Call: +61 1800 445 007  
eMail: supportpc12@pilatus.com.au

**Attachments:** P&WC SIL PT6A-218R1

INTENTIONALLY BLANK



# SERVICE INFORMATION LETTER

**Subject:** Filter Element Option PN 3059778-01 physically marked IC PN 3059779-01

**Applicability:**

PT6A-11 /-110 /-112 /-114 /-114A /-11AG /-121 /-135 /-135A /-140 /-15AG /-20 /-20A /-20B /-21 /-25 /-25A /-25C /-27 /-28 /-34 /-34AG /-35 /-36 /-38 /-41 /-42 /-42A /-45A /-45B /-45R /-50 /-52 /-6 /-60A /-60AG /-61 /-62 /-64 /-65AG /-65AR /-65B /-65R /-66 /-66A /-66B /-66D /-67 /-67A /-67AF /-67AG /-67B /-67D /-67P /-67R /-67T /-68 /-68B /-68C /-6A /-6B

Pratt & Whitney Canada has determined that a number of non-cleanable filter elements, part number 3059778-01, have been incorrectly identified with the interchangeability (IC) part number 3059779-01 (Figure 1) for which the 3059778-01 is an option.



**Figure 1**

The integrity and functionality of these filter elements is in no way affected. The misidentification does not affect parts serviceability and installed filters remain subject to the current, applicable Engine Maintenance Manual criteria.

P&WC has contacted customers via a Spare Parts Recall Letter dated 28 March 2014 to request they inspect parts remaining on their shelf for the affected lot # 401314 (Figure 2). P&WC requests that any nonconforming filter elements found in stock are returned through your source of supply in order to obtain credit consideration.

This Service Information Letter is valid for one year from date of issue.

**EXPORT CONTROL CLASSIFICATION:** This document does not contain technical data.

ISSUED: APR 17/2014

REVISED: APR 21/2014

**PRATT & WHITNEY CANADA  
SERVICE INFORMATION LETTER**

S.I.L NO. PT6A-218 R1



**Figure 2**

P&WC and the filter supplier have inspected available stock and purged all nonconforming material.

Sincerely  
PRATT & WHITNEY CANADA CORP.

A handwritten signature in black ink, appearing to read 'Gerry Whitty', written over a horizontal line.

Gerry Whitty  
Deputy Chief Engineer  
Customer Service