



PILATUS AIRCRAFT LTD. CH-6371 STANS, SWITZERLAND

SERVICE LETTER

SUBJECT: P&WC SERVICE INFORMATION LETTER NO. PT6A-034R4 - ENGINES, DISCOLORED OIL

To all Customers and Operators:

Date: Sep 25/98

This Service Letter is issued to draw attention to the following vendor information:

P&WC Service Information Letter No. PT6A-034R4 - Engines, Discolored Oil.

P&WC Temporary Revision No's 72-26, 72-27, 72-28 and 72-29 (all dated Aug. 26/98) for the Maintenance Manual, Chapter 72-00-00, Engine Turboprop - Fault Isolation.

NOTE: This Service Letter supersedes PILATUS Service Letter PC-12-030, dated December 19/97.

Pilatus recommends the incorporation of the P&WC Service Information Letter No. PT6A-034R4 - Engines, Discolored Oil. Note that P&WC have revised the recommended life of the main engine oil filter to 300 hours, to reduce the risk of gradual filter blockage due to a build-up of carbon in the oil.

If you have not received these documents direct from the vendor, please contact them at the address given below:

Pratt and Whitney Canada Inc.
1000, Marie-Victorin
Longueuil, Québec
Canada J4G 1A1 Tel: 514-677-9411

Operators requiring further information on this subject, please contact the address given below:

PILATUS AIRCRAFT LTD,
CUSTOMER LIAISON MANAGER,
CH 6371 STANS Tel: +41 41 619 63 19
SWITZERLAND Fax:+41 41 610 33 51

