

SUBJECT: PC-12/47E Aircraft - New Left Hand Power Junction Box

To all Customers, Operators and Service Centers:

Date: Apr 04/11

This Service Letter is issued to draw attention to the following information:

Effective from aircraft MSN 1305, a new Left Hand Power Junction Box (LHPJB) is introduced. The new unit incorporates an improved bus-tie system and has these part numbers:

- Pilatus P/N 974.03.38.144
- Vendor P/N FE1549L-01

Upgrades for the existing LHPJB P/N 974.03.38.136 to P/N 974.03.38.144 will be available starting August 2011 at a rate of 5 units per month. Please contact your local Service Center for scheduling of upgrades.

The current LHPJB P/N 974.03.38.136 is now superseded and will be replaced on attrition with the new LHPJB.

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD.,
CUSTOMER SUPPORT MANAGER,
CH-6371 STANS,
SWITZERLAND.

General Aviation
Tel : + 41 41 619 6208
Fax: + 41 41 619 7311
eMail: SupportPC12@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,
PRODUCT SUPPORT DEPARTMENT,
11755 AIRPORT WAY,
BROOMFIELD, CO 80021.
USA

Tel : 303 465 9099
Fax: 303 465 6040
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD.,
17 James Schofield Drive,
Adelaide Airport SA 5950,
AUSTRALIA

Tel : +61 (08) 8234 4433
Fax: +61 (08) 8234 4499
Free Call: 1800 445 007
eMail: SupportPC12@pilatus.com.au

INTENTIONALLY BLANK