

PILATUS AIRCRAFT LTD. STANS, SWITZERLAND

## SERVICE LETTER

## **PC-12**

## SUBJECT: NOSE LANDING GEAR POSITION INDICATION LIGHT FLICKERING AFTER MODIFICATION OF THE TRANSPONDER SYSTEM

To all Customers, Operators and Service Centers:

Date: Jul 08/16

Effectivity: All PC-12, PC-12/45, PC-12/47 aircraft with proximity switch P/N 973.30.33.111 installed for nose landing gear position sensing.

This Service Letter is issued to draw attention to a possible interference between certain transponder systems and the proximity switch P/N 973.30.33.111, which may lead to the nose landing gear position indication light flickering.

It has been reported that after modification of the transponder system, the NLG position indication light flickered intermittently. Investigation found that some transponder systems emit signals which interfere with the proximity switch P/N 973.30.33.111. This interference causes the flickering.

If the NLG position indication light flickers after modification of the transponder system, Service Centers are advised to replace the affected proximity switch P/N 973.30.33.111 with the newer design switch P/N 973.30.33.116. The newer switch is more resistant to interference and has been found to give reliable NLG position indication.

The proximity switch P/N 973.30.33.116 will be introduced into the relevant Illustrated Parts Catalogue at the next revision. If the NLG position light flickering is experienced before the revised IPC is published, please contact Pilatus Customer Support and suitable documentation will be provided.

Operators who require further information on this subject should contact the address given below.

PILATUS AIRCRAFT LTD CUSTOMER SUPPORT MANAGER CH-6371 STANS SWITZERLAND General Aviation Tel: +41 41 619 3333 Fax: +41 41 619 7311 eMail: SupportPC12@pilatus-aircraft.com PILATUS BUSINESS AIRCRAFT LTD PRODUCT SUPPORT DEPARTMENT 11755 AIRPORT WAY BROOMFIELD, CO 80021 UNITED STATES OF AMERICA Tel: +1 303 465 9099 Fax: +1 303 465 6040

eMail: SupportPC12@PilBal.com

PILATUS AUSTRALIA PTY LTD 17 JAMES SCHOFIELD DRIVE ADELAIDE AIRPORT SA 5950 AUSTRALIA

Tel: +61 8 8238 1600 Fax: +61 8 8234 4499 Free Call: +61 1800 PILATUS (745 2887) eMail: SupportPC12@pilatus.com.au



SERVICE LETTER



INTENTIONALLY BLANK

Service Letter 187 Page 2 of 2